

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15649

Make	KIA
Model	K 2700 WORKHORSE P/U S/C
Vin	KNCSHX71LN7556972
Engine Specifications	Diesel
Vehicle Type	P/U
Service Plan	N/A

Year	2021
Km	81180
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior Radio / Entertainment Within Specification Image: Cluster Aircon Controls Within Specification Image: Cluster Cluster Within Specification Image: Cluster Image: Cluster Image: Cluster Within Specification Image: Cluster <

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION

218110					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Within Specification	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	•	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	•	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	•	Multi V belt	Within Specification	•
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Within Specification	-
Rear Linings	80%	-
Brake Master	Within Specification	-
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Not Applicable	•
Aircon Pump	Not Applicable	•
Aircon Condensor	Not Applicable	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	-
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	-
Stabilizer Links	Within Specification	-
Wheel Bearings	Within Specification	-
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	-
Sideshafts/Seal	Not Applicable	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	-
Tyres & Spare	Within Specification	-
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	-
Clutch Slave	Within Specification	-
Clutch Cable	Within Specification	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	-
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	•
Cyl Leakage Test	Within Specification	•
Road Test	Within Specification	•
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

