



Make	MERCEDES-BENZ
Model	VITO 111 1.6 CDI F/C P/V
Vin	WDF44760323499384
Engine Specifications	1.6 Diesel <input type="checkbox"/>
Vehicle Type	P/V
Service Plan	N/A

Year	2018
Km	110127
Transmission	Manual <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

Radio / Entertainment	Not Applicable <input type="checkbox"/>	Aircon Controls	Not Applicable <input type="checkbox"/>
Cluster	Good Condition <input type="checkbox"/>	Electric Windows	Good Condition <input type="checkbox"/>

Exterior

Windscreen	Good Condition <input type="checkbox"/>	Mag Wheels	Not Applicable <input type="checkbox"/>
Side Mirrors / Electric	Not Applicable <input type="checkbox"/>	Wiper Blades	Good Condition <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	110127 Km	Dip Stick	Good Condition <input type="checkbox"/>
Oil Filter	Good Condition <input type="checkbox"/>	Oil Filler Cap	Good Condition <input type="checkbox"/>
Fuel/Diesel Filter	Good Condition <input type="checkbox"/>	Fan Belt	Good Condition <input type="checkbox"/>
Air Filter	Good Condition <input type="checkbox"/>	Fan belt Tensioner	Good Condition <input type="checkbox"/>
Cabin Filter	Not Applicable <input type="checkbox"/>	Alternator Belt	Good Condition <input type="checkbox"/>
Spark Plugs	Not Applicable <input type="checkbox"/>	Power Steering Belt	Good Condition <input type="checkbox"/>
Brake Fluid	Good Condition <input type="checkbox"/>	Aircon Belt	Good Condition <input type="checkbox"/>
Antifreeze	Good Condition <input type="checkbox"/>	Multi V belt	Good Condition <input type="checkbox"/>
Rear Main Seal	Good Condition <input type="checkbox"/>	Engine Mountings	Good Condition <input type="checkbox"/>
Sump/Gasket	Good Condition <input type="checkbox"/>	PCV Valve	Good Condition <input type="checkbox"/>

Braking System		
Front Brake Pads	100%	<input type="checkbox"/>
Front Brake Discs	Good Condition	<input type="checkbox"/>
Front Brake Sensor	Good Condition	<input type="checkbox"/>
Rear Brake Pads	80%	<input type="checkbox"/>
Rear Brake Discs	Good Condition	<input type="checkbox"/>
Rear Brake Sensor	Good Condition	<input type="checkbox"/>
Rear Drums	No Visible Leaks	<input type="checkbox"/>
Rear Linings	-Select-	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	Good Condition	<input type="checkbox"/>

Cooling System		
Radiator	Good Condition	<input type="checkbox"/>
Radiator Hoses	Good Condition	<input type="checkbox"/>
Waterpump	Good Condition	<input type="checkbox"/>
Thermostat	Good Condition	<input type="checkbox"/>
Aircon Gas	Not Applicable	<input type="checkbox"/>
Aircon Pump	Not Applicable	<input type="checkbox"/>
Aircon Condensor	Not Applicable	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	Good Condition	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Good Condition	<input type="checkbox"/>
Injectors	Good Condition	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	Good Condition	<input type="checkbox"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="checkbox"/>
Glow Plugs	Good Condition	<input type="checkbox"/>
Distrubutor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	▼
Power Steering Pump	Good Condition	▼
Wheel Alignment	Good Condition	▼
CV Joints	Good Condition	▼
CV Boots	Good Condition	▼
Shocks Front	Good Condition	▼
Shock Mountings Front	Good Condition	▼
Shocks Rear	Good Condition	▼
Stabilizer Links	Good Condition	▼
Wheel Bearings	Good Condition	▼
Bearing Hubs	Good Condition	▼
Control Arms	Good Condition	▼
Sideshafts/Seal	Good Condition	▼
Propshaft	Good Condition	▼
Wheel Nuts/Studs	Good Condition	▼
Tyres & Spare	Good Condition	▼
Mag Wheels/Hub Caps	Good Condition	▼

Transmission & Clutch		
Clutch Kit	Good Condition	▼
Clutch Master	Good Condition	▼
Clutch Slave	Good Condition	▼
Clutch Cable	Not Applicable	▼
Gearbox	Good Condition	▼
Gear & Diff oil	Good Condition	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Good Condition	▼
Gear Linkages	Good Condition	▼

Ignition System		
Diagnostics	Good Condition	▼
Cyl Leakage Test	Good Condition	▼
Road Test	Good Condition	▼
Handling	Good Condition	▼

Concluding Remarks

Bosch Technician

Basal Johnson ▼

General Comments

NEW Technician

Date of Inspection

25-Mar-2024