



Make	MERCEDES-BENZ
Model	VITO 111 1.6 CDI F/C P/V
Vin	WDF44760323499979
Engine Specifications	1.6 Diesel <input type="checkbox"/>
Vehicle Type	P/V
Service Plan	N/A

Year	2018
Km	122003
Transmission	Manual <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

Radio / Entertainment	Not Applicable <input type="checkbox"/>	Aircon Controls	Good Condition <input type="checkbox"/>
Cluster	Good Condition <input type="checkbox"/>	Electric Windows	Good Condition <input type="checkbox"/>

Exterior

Windscreen	Good Condition <input type="checkbox"/>	Mag Wheels	Not Applicable <input type="checkbox"/>
Side Mirrors / Electric	Good Condition <input type="checkbox"/>	Wiper Blades	Good Condition <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		Km	Dip Stick	Good Condition <input type="checkbox"/>
Oil Filter	No Visible Leaks <input type="checkbox"/>		Oil Filler Cap	Good Condition <input type="checkbox"/>
Fuel/Diesel Filter	No Visible Leaks <input type="checkbox"/>		Fan Belt	Good Condition <input type="checkbox"/>
Air Filter	Good Condition <input type="checkbox"/>		Fan belt Tensioner	Good Condition <input type="checkbox"/>
Cabin Filter	Good Condition <input type="checkbox"/>		Alternator Belt	Good Condition <input type="checkbox"/>
Spark Plugs	Not Applicable <input type="checkbox"/>		Power Steering Belt	Good Condition <input type="checkbox"/>
Brake Fluid	Good Condition <input type="checkbox"/>		Aircon Belt	Good Condition <input type="checkbox"/>
Antifreeze	Good Condition <input type="checkbox"/>		Multi V belt	Good Condition <input type="checkbox"/>
Rear Main Seal	No Visible Leaks <input type="checkbox"/>		Engine Mountings	Good Condition <input type="checkbox"/>
Sump/Gasket	No Visible Leaks <input type="checkbox"/>		PCV Valve	Good Condition <input type="checkbox"/>

Braking System		
Front Brake Pads	80%	<input type="checkbox"/>
Front Brake Discs	Good Condition	<input type="checkbox"/>
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	80%	<input type="checkbox"/>
Rear Brake Discs	Good Condition	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Good Condition	<input type="checkbox"/>
Rear Linings	60%	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	No Visible Leaks	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	Not Applicable	<input type="checkbox"/>
Aircon Pump	Not Applicable	<input type="checkbox"/>
Aircon Condensor	Not Applicable	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	No Visible Leaks	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Good Condition	<input type="checkbox"/>
Injectors	Good Condition	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	Good Condition	<input type="checkbox"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="checkbox"/>
Glow Plugs	Good Condition	<input type="checkbox"/>
Distrubutor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>



Steering & Suspension		
Steering Rack	No Visible Leaks	<input type="button" value="v"/>
Power Steering Pump	No Visible Leaks	<input type="button" value="v"/>
Wheel Alignment	Good Condition	<input type="button" value="v"/>
CV Joints	Good Condition	<input type="button" value="v"/>
CV Boots	Good Condition	<input type="button" value="v"/>
Shocks Front	Good Condition	<input type="button" value="v"/>
Shock Mountings Front	Good Condition	<input type="button" value="v"/>
Shocks Rear	Good Condition	<input type="button" value="v"/>
Stabilizer Links	Good Condition	<input type="button" value="v"/>
Wheel Bearings	Good Condition	<input type="button" value="v"/>
Bearing Hubs	Good Condition	<input type="button" value="v"/>
Control Arms	Good Condition	<input type="button" value="v"/>
Sideshafts/Seal	Good Condition	<input type="button" value="v"/>
Propshaft	Not Applicable	<input type="button" value="v"/>
Wheel Nuts/Studs	Good Condition	<input type="button" value="v"/>
Tyres & Spare	Good Condition	<input type="button" value="v"/>
Mag Wheels/Hub Caps	Good Condition	<input type="button" value="v"/>

Transmission & Clutch		
Clutch Kit	Good Condition	<input type="button" value="v"/>
Clutch Master	Good Condition	<input type="button" value="v"/>
Clutch Slave	Good Condition	<input type="button" value="v"/>
Clutch Cable	Not Applicable	<input type="button" value="v"/>
Gearbox	Good Condition	<input type="button" value="v"/>
Gear & Diff oil	Not Applicable	<input type="button" value="v"/>
Auto Transmission	Not Applicable	<input type="button" value="v"/>
Gear Selector	Good Condition	<input type="button" value="v"/>
Gear Linkages	Good Condition	<input type="button" value="v"/>

Ignition System		
Diagnostics	-Select-	<input type="button" value="v"/>
Cyl Leakage Test	-Select-	<input type="button" value="v"/>
Road Test	-Select-	<input type="button" value="v"/>
Handling	-Select-	<input type="button" value="v"/>

Concluding Remarks

Bosch Technician

-Select-

General Comments

NEW Technician

SHAUN OLIVIER

Date of Inspection

