Make	FORD		
Model	RANGER 3.2TI	DCi WILDTRAK A/T P/U	D/C
Vin	AFAPXXMJ2PJ	M14834	
Engine Specifications	3.2	Diesel	▼
Vehicle Type	D/C		
Service Plan	N/A		

Year	2018
Km	124225
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>—</b>	Aircon Controls	Within Specification	<b>~</b>
Cluster	Within Specification	lacksquare	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	<b>~</b>	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	<b>~</b>	Wiper Blades	Within Specification	<b>~</b>

	BOSCH VEHIC	:LI	E INSPECTION		
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	No Visible Leaks	
Oil Filter	Within Specification		Oil Filler Cap	Within Specification	lacksquare
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	lacksquare
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	lacksquare
Spark Plugs	Not Applicable		Power Steering Belt	No Cracks	
Brake Fluid	Within Specification		Aircon Belt	No Cracks	•
Antifreeze	Within Specification		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks   ▼		Engine Mountings	Within Specification	
Sump/Gasket	No Visible Leaks   ▼		PCV Valve	Within Specification	

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Within Specification	-
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	-

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	▼
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>—</b>
Power Steering Pump	Within Specification	<b>—</b>
Wheel Alignment	Within Specification	<b>—</b>
CV Joints	Within Specification	<b>—</b>
CV Boots	Within Specification	<b>—</b>
Shocks Front	Within Specification	<b>—</b>
Shock Mountings Front	Within Specification	<b>—</b>
Shocks Rear	Within Specification	<b>V</b>
Stabilizer Links	Within Specification	<b>—</b>
Wheel Bearings	Within Specification	<b>—</b>
Bearing Hubs	Within Specification	<b>•</b>
Control Arms	Within Specification	<b>—</b>
Sideshafts/Seal	No Visible Leaks	<b>—</b>
Propshaft	Within Specification	<b>V</b>
Wheel Nuts/Studs	Within Specification	<b>V</b>
Tyres & Spare	Within Specification	<b>V</b>
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	
Clutch Cable	Not Applicable	
Gearbox	Within Specification	lacksquare
Gear & Diff oil	Within Specification	
Auto Transmission	Within Specification	
Gear Selector	Within Specification	
Gear Linkages	Not Applicable	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	<b>—</b>

Concluding Remarks		

Bosch Technician	
Luandre Swanepoel	•

General Comments		

NEW Technician		
	•	

Date of Inspection
23-Mar-2024



