

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-03-29 10:10:06
Technician Name:Riaan
Order no:
Service fee:
Notes:

Vehicle Information

Year:2021
Make:EUROFORD
Model:EcoSport
VIN:MAJAXXMRKAMB33623
Displacement:G 1.0 MPI KAPPA
Odometer:46396 km
Vehicle Software Version:V10.62

Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.GWM (Gateway Module A)
- 6.HVAC (Heating Ventilation Air Conditioning)
- 7.IPC (Instrument Panel Control Module)
- 8.PAM (Parking Aid Module)
- 9.PCM (Powertrain Control Module)
- 10.PSCM (Power Steering Control Module)
- 11.RCM (Restraint Control Module)
- 12.SCCM (Steering Column Control Module)