

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: lucas@boschgezina.co.za
Sn: 988579800333
Time: 2024-03-26 12:59:05
Technician Name: Wimpie F
Order no:
Service fee:
Notes:

Vehicle Information

Make: RENAULT
Model: KWID
VIN: MEEBBA00400744953
Displacement: G 1.2 MPI KAPPA
Odometer: 45243 km
Vehicle Software Version: V10.36

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS (Anti-lock Braking System)
3. IC (Instrument Cluster)
4. UCH
5. SRS (Supplemental Inflatable Restraint System)
6. Variable P.A.S
7. Radio