

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-03-15 14:14:07
Technician Name: mike
Customer Name: citton cars

Vehicle Information

Year: 2019
Make: HYUNDAI
Model: i20(IB)
VIN: MALBM51BLKM513969
Displacement: G 1.2 MPI
Odometer: 92197 km
Vehicle Software Version: V10.30

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS (Anti-lock Braking System)
3. Airbag (Event #1)
4. Airbag (Event #2)
5. Body Control Module
6. Cluster Module
7. EPS (Electronic Power Steering)
8. IMM (Immobilizer)
9. CODE (Transmitter Code Saving)