



Make	MERCEDES-BENZ
Model	VITO 116 2.0 CDI TOURER PRO A/T
Vin	W1V44770324148394
Engine Specifications	2.0 Diesel <input type="checkbox"/>
Vehicle Type	B/S
Service Plan	N/A

Year	2022
Km	39723
Transmission	Automatic <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

Radio / Entertainment	Good Condition <input type="checkbox"/>	Aircon Controls	Good Condition <input type="checkbox"/>
Cluster	Good Condition <input type="checkbox"/>	Electric Windows	Good Condition <input type="checkbox"/>

Exterior

Windscreen	Good Condition <input type="checkbox"/>	Mag Wheels	Good Condition <input type="checkbox"/>
Side Mirrors / Electric	Good Condition <input type="checkbox"/>	Wiper Blades	Renewed <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		Km	Dip Stick	Good Condition <input type="checkbox"/>
Oil Filter	-Select-	<input type="checkbox"/>	Oil Filler Cap	Good Condition <input type="checkbox"/>
Fuel/Diesel Filter	-Select-	<input type="checkbox"/>	Fan Belt	Good Condition <input type="checkbox"/>
Air Filter	-Select-	<input type="checkbox"/>	Fan belt Tensioner	Good Condition <input type="checkbox"/>
Cabin Filter	Within Specification	<input type="checkbox"/>	Alternator Belt	Good Condition <input type="checkbox"/>
Spark Plugs	Not Applicable	<input type="checkbox"/>	Power Steering Belt	Good Condition <input type="checkbox"/>
Brake Fluid	Within Specification	<input type="checkbox"/>	Aircon Belt	Good Condition <input type="checkbox"/>
Antifreeze	Within Specification	<input type="checkbox"/>	Multi V belt	Good Condition <input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Good Condition <input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Good Condition <input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="checkbox"/>
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	No Fault Code	<input type="checkbox"/>
Rear Brake Pads	60%	<input type="checkbox"/>
Rear Brake Discs	Within Specification	<input type="checkbox"/>
Rear Brake Sensor	No Fault Code	<input type="checkbox"/>
Rear Drums	Within Specification	<input type="checkbox"/>
Rear Linings	80%	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	Good Condition	<input type="checkbox"/>

Cooling System		
Radiator	Good Condition	<input type="checkbox"/>
Radiator Hoses	Good Condition	<input type="checkbox"/>
Waterpump	Good Condition	<input type="checkbox"/>
Thermostat	Good Condition	<input type="checkbox"/>
Aircon Gas	Good Condition	<input type="checkbox"/>
Aircon Pump	Good Condition	<input type="checkbox"/>
Aircon Condensor	Good Condition	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	Good Condition	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Good Condition	<input type="checkbox"/>
Injectors	Good Condition	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	Good Condition	<input type="checkbox"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="checkbox"/>
Glow Plugs	Good Condition	<input type="checkbox"/>
Distrubutor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>



Steering & Suspension		
Steering Rack	Good Condition	▼
Power Steering Pump	Good Condition	▼
Wheel Alignment	Good Condition	▼
CV Joints	Good Condition	▼
CV Boots	No Visible Leaks	▼
Shocks Front	Good Condition	▼
Shock Mountings Front	Good Condition	▼
Shocks Rear	Good Condition	▼
Stabilizer Links	Good Condition	▼
Wheel Bearings	Good Condition	▼
Bearing Hubs	Good Condition	▼
Control Arms	Good Condition	▼
Sideshafts/Seal	No Visible Leaks	▼
Propshaft	Good Condition	▼
Wheel Nuts/Studs	Good Condition	▼
Tyres & Spare	Good Condition	▼
Mag Wheels/Hub Caps	Good Condition	▼

Transmission & Clutch		
Clutch Kit	Not Applicable	▼
Clutch Master	Not Applicable	▼
Clutch Slave	Not Applicable	▼
Clutch Cable	Not Applicable	▼
Gearbox	Good Condition	▼
Gear & Diff oil	Good Condition	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Good Condition	▼
Gear Linkages	Good Condition	▼

Ignition System		
Diagnostics	Good Condition	▼
Cyl Leakage Test	Within Specification	▼
Road Test	Good Condition	▼
Handling	Good Condition	▼

Concluding Remarks

Bosch Technician

-Select- ▼

General Comments

NEW Technician

HENDRIE

Date of Inspection

04-Mar-2024

