Make	MAHINDRA		
Model	KUV 100 1.2 K2+ #DARE		
Vin	MA1VC2RBCL608	35219	
Engine Specifications	1.2	Petrol	•
Vehicle Type	SUV		
Service Plan	N/A		

Year	2020
Km	45809
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	~	Mag Wheels	Good Condition	—
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	_	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	lacksquare	Fan Belt	Good Condition	V
Air Filter	Good Condition	-	Fan belt Tensioner	Good Condition	~
Cabin Filter	Good Condition	—	Alternator Belt	Good Condition	V
Spark Plugs	Good Condition	lacksquare	Power Steering Belt	Good Condition	~
Brake Fluid	Good Condition	V	Aircon Belt	Good Condition	~
Antifreeze	Good Condition	•	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	lacksquare	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	~	PCV Valve	Good Condition	~

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	—
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	-
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	lacksquare
Turbo	Not Applicable	•
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	lacksquare
Wheel Alignment	Good Condition	lacksquare
CV Joints	Good Condition	V
CV Boots	Good Condition	•
Shocks Front	Good Condition	~
Shock Mountings Front	Good Condition	—
Shocks Rear	Good Condition	~
Stabilizer Links	Good Condition	~
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	—
Wheel Nuts/Studs	Good Condition	—
Tyres & Spare	Good Condition	—
Mag Wheels/Hub Caps	Good Condition	—

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	-Select-	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	-Select-	•
Cyl Leakage Test	-Select-	~
Road Test	-Select-	~
Handling	-Select-	~

Concluding Remarks		

Bosch Technician	
-Select-	_

General Comments		

NEW Technician
SHAUN OLIVIER

Date of Inspection



