

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:karika@boschgezina.co.za
Sn:988579800333
Time:2024-03-22 16:46:44
Technician Name:shaun
Order no:
Service fee:
Notes:

Vehicle Information

Make:INDIANMAHINDRA
Displacement:G 1.2 MPI KAPPA
Odometer:45810 km
Vehicle Software Version:V10.34

Inspection Result

The following systems are OK:

- 1.EMS(ENGINE MANAGEMENT SYSTEM)
- 2.IC(INSTRUMENT CLUSTER)
- 3.IMMOBILISER
- 4.SRS(SUPPLEMENTARY RESTRAINT SYSTEM)
- 5.ABS(ANTI-LOCK BRAKING SYSTEM)