



| | |
|-----------------------|-------------------------------------|
| Make | FORD |
| Model | ECOSPORT 1.5TDCi TREND |
| Vin | MAJAXXMRKAGA70708 |
| Engine Specifications | 1.5 Diesel <input type="checkbox"/> |
| Vehicle Type | SUV |
| Service Plan | N/A |

| | |
|---------------|---------------------------------|
| Year | 2016 |
| Km | 115565 |
| Transmission | Manual <input type="checkbox"/> |
| Colour | WHITE |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

Interior

| | | | |
|-----------------------|--|------------------|--|
| Radio / Entertainment | Working Condition <input type="checkbox"/> | Aircon Controls | Working Condition <input type="checkbox"/> |
| Cluster | Working Condition <input type="checkbox"/> | Electric Windows | Working Condition <input type="checkbox"/> |

Exterior

| | | | |
|-------------------------|---|--------------|---|
| Windscreen | Good Condition <input type="checkbox"/> | Mag Wheels | Good Condition <input type="checkbox"/> |
| Side Mirrors / Electric | Good Condition <input type="checkbox"/> | Wiper Blades | Good Condition <input type="checkbox"/> |

BOSCH VEHICLE INSPECTION

Engine

| | | | | |
|--------------------|---|----|---------------------|---|
| Oil Service | | Km | Dip Stick | Good Condition <input type="checkbox"/> |
| Oil Filter | No Visible Leaks <input type="checkbox"/> | | Oil Filler Cap | Good Condition <input type="checkbox"/> |
| Fuel/Diesel Filter | No Visible Leaks <input type="checkbox"/> | | Fan Belt | Good Condition <input type="checkbox"/> |
| Air Filter | Good Condition <input type="checkbox"/> | | Fan belt Tensioner | Good Condition <input type="checkbox"/> |
| Cabin Filter | Good Condition <input type="checkbox"/> | | Alternator Belt | Good Condition <input type="checkbox"/> |
| Spark Plugs | Not Applicable <input type="checkbox"/> | | Power Steering Belt | Good Condition <input type="checkbox"/> |
| Brake Fluid | Good Condition <input type="checkbox"/> | | Aircon Belt | Good Condition <input type="checkbox"/> |
| Antifreeze | Good Condition <input type="checkbox"/> | | Multi V belt | Good Condition <input type="checkbox"/> |
| Rear Main Seal | Good Condition <input type="checkbox"/> | | Engine Mountings | Good Condition <input type="checkbox"/> |
| Sump/Gasket | Good Condition <input type="checkbox"/> | | PCV Valve | Good Condition <input type="checkbox"/> |

| Braking System | | |
|--------------------|------------------|--------------------------|
| Front Brake Pads | 60% | <input type="checkbox"/> |
| Front Brake Discs | Good Condition | <input type="checkbox"/> |
| Front Brake Sensor | Not Applicable | <input type="checkbox"/> |
| Rear Brake Pads | -Select- | |
| Rear Brake Discs | Not Applicable | <input type="checkbox"/> |
| Rear Brake Sensor | Not Applicable | <input type="checkbox"/> |
| Rear Drums | Good Condition | <input type="checkbox"/> |
| Rear Linings | 60% | <input type="checkbox"/> |
| Brake Master | No Visible Leaks | <input type="checkbox"/> |
| Hand Brake | Good Condition | <input type="checkbox"/> |
| Brake Calipers | Good Condition | <input type="checkbox"/> |
| Brake Hose | No Visible Leaks | <input type="checkbox"/> |

| Cooling System | | |
|-------------------|----------------|--------------------------|
| Radiator | Good Condition | <input type="checkbox"/> |
| Radiator Hoses | Good Condition | <input type="checkbox"/> |
| Waterpump | Good Condition | <input type="checkbox"/> |
| Thermostat | Good Condition | <input type="checkbox"/> |
| Aircon Gas | Good Condition | <input type="checkbox"/> |
| Aircon Pump | Good Condition | <input type="checkbox"/> |
| Aircon Condensor | Good Condition | <input type="checkbox"/> |
| Interior Fan | Good Condition | <input type="checkbox"/> |
| Interior Radiator | Good Condition | <input type="checkbox"/> |

| Fueling System | | |
|-----------------|------------------|--------------------------|
| Intake Manifold | Good Condition | <input type="checkbox"/> |
| Throttle | Good Condition | <input type="checkbox"/> |
| Turbo | Good Condition | <input type="checkbox"/> |
| Injectors | No Visible Leaks | <input type="checkbox"/> |
| Fuel Pump | No Visible Leaks | <input type="checkbox"/> |
| Fuel Lines | No Visible Leaks | <input type="checkbox"/> |

| Ignition System | | |
|-----------------|----------------|--------------------------|
| Ignition Coils | Not Applicable | <input type="checkbox"/> |
| Glow Plugs | Good Condition | <input type="checkbox"/> |
| Distrubutor | Not Applicable | <input type="checkbox"/> |
| HT Leads | Not Applicable | <input type="checkbox"/> |

| Steering & Suspension | | |
|-----------------------|----------------|----------------------------------|
| Steering Rack | Good Condition | <input type="button" value="v"/> |
| Power Steering Pump | Good Condition | <input type="button" value="v"/> |
| Wheel Alignment | Good Condition | <input type="button" value="v"/> |
| CV Joints | Good Condition | <input type="button" value="v"/> |
| CV Boots | Good Condition | <input type="button" value="v"/> |
| Shocks Front | Good Condition | <input type="button" value="v"/> |
| Shock Mountings Front | Good Condition | <input type="button" value="v"/> |
| Shocks Rear | Renewed | <input type="button" value="v"/> |
| Stabilizer Links | Good Condition | <input type="button" value="v"/> |
| Wheel Bearings | Good Condition | <input type="button" value="v"/> |
| Bearing Hubs | Good Condition | <input type="button" value="v"/> |
| Control Arms | Good Condition | <input type="button" value="v"/> |
| Sideshafts/Seal | Good Condition | <input type="button" value="v"/> |
| Propshaft | Not Applicable | <input type="button" value="v"/> |
| Wheel Nuts/Studs | Good Condition | <input type="button" value="v"/> |
| Tyres & Spare | Good Condition | <input type="button" value="v"/> |
| Mag Wheels/Hub Caps | Good Condition | <input type="button" value="v"/> |

| Transmission & Clutch | | |
|-----------------------|----------------|----------------------------------|
| Clutch Kit | Good Condition | <input type="button" value="v"/> |
| Clutch Master | Good Condition | <input type="button" value="v"/> |
| Clutch Slave | Good Condition | <input type="button" value="v"/> |
| Clutch Cable | Not Applicable | <input type="button" value="v"/> |
| Gearbox | Good Condition | <input type="button" value="v"/> |
| Gear & Diff oil | Not Applicable | <input type="button" value="v"/> |
| Auto Transmission | Not Applicable | <input type="button" value="v"/> |
| Gear Selector | Good Condition | <input type="button" value="v"/> |
| Gear Linkages | Good Condition | <input type="button" value="v"/> |

| Ignition System | | |
|------------------|----------|----------------------------------|
| Diagnostics | -Select- | <input type="button" value="v"/> |
| Cyl Leakage Test | -Select- | <input type="button" value="v"/> |
| Road Test | -Select- | <input type="button" value="v"/> |
| Handling | -Select- | <input type="button" value="v"/> |

Concluding Remarks

Bosch Technician

-Select-

General Comments

NEW Technician

SHAUN OLIVIER

Date of Inspection
