

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:juan-dre@boschgezina.co.za  
Sn:988579800333  
Time:2024-04-04 12:53:21  
Technician Name:shaun  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2016  
Make:USAFORD  
Model:EcoSport  
VIN:MAJAXXMRKAGA70708  
Displacement:G 1.1 SOHC  
Odometer:115569 km  
Vehicle Software Version:V10.76

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.FCDIM (Front Control/Display Interface Module)
- 6.IPC (Instrument Panel Control Module)
- 7.PCM (Powertrain Control Module)
- 8.PSCM (Power Steering Control Module)
- 9.RCM (Restraint Control Module)