

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 14097

Make	FIAT		
Model	500 1.2 CABRIOLET		
Vin	ZFA3120000J057160		
Engine Specifications	1.2	Petrol	
Vehicle Type	C/B		

Year	2013
Km	110774
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Within Specification	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Not Applicable	-	Mag Wheels	Not Applicable	-
Side Mirrors / Electric	Not Applicable	•	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION

Oil Service	1	10774 Km	Dip Stick	No Visible Leaks	-
Oil Filter Re	enewed	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter W	/ithin Specification	-	Fan Belt	Renewed	•
Air Filter W	/ithin Specification	-	Fan belt Tensioner	Good Condition	•
Cabin Filter W	/ithin Specification	-	Alternator Belt	Not Applicable	•
Spark Plugs W	/ithin Specification	-	Power Steering Belt	Not Applicable	•
Brake Fluid W	/ithin Specification	-	Aircon Belt	Not Applicable	•
Antifreeze W	/ithin Specification	-	Multi V belt	Not Applicable	•
Rear Main Seal No	o Visible Leaks	-	Engine Mountings	Good Condition	-
Sump/Gasket No	o Visible Leaks	•	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	60%	-
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Within Specification	-
Rear Linings	60%	-
Brake Master	Good Condition	•
Hand Brake	Good Condition	-
Brake Calipers	Good Condition	-
Brake Hose	Good Condition	-

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	-
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

JOB CARD NUMBER 14097

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	-
Shocks Front	Within Specification	-
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	-
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	-
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Good Condition	•
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection

19-Jun-2024



HENDRIE

BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

