

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:johan@boschgezina.co.za  
Sn:988579800333  
Time:2024-03-30 10:45:13  
Technician Name:shaun  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2017  
Make:HYUNDAI  
Model:Creta(GS)  
VIN:MALC381CLHM224443  
Displacement:G 1.6 MPI  
Odometer:119276 km  
Vehicle Software Version:V10.30

## Inspection Result

The following systems are OK:

- 1.ECM(Engine Control Module)-Leaded All
- 2.ECM(Engine Control Module)-Unleaded All
- 3.ABS (Anti-lock Braking System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.Body Control Module
- 7.Cluster Module
- 8.Smart Junction Block
- 9.EPS (Electronic Power Steering)
- 10.IMM (Immobilizer)
- 11.CODE (Transmitter Code Saving)