



Make	NISSAN	
Model	HARDBODY NP300 2.0i LWB P/U S/C	
Vin	ADNALGD22ZR095167	
Engine Specifications	2.0	Petrol <input type="checkbox"/>
Vehicle Type	S/C	
Service Plan	N/A	

Year	2017	
Km	72292	
Transmission	Manual	<input type="checkbox"/>
Colour	WHITE	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Renewed	<input type="checkbox"/>	Aircon Controls	Within Specification	<input type="checkbox"/>
Cluster	Working Condition	<input type="checkbox"/>	Electric Windows	Not Applicable	<input type="checkbox"/>

Exterior

Windscreen	Within Specification	<input type="checkbox"/>	Mag Wheels	Not Applicable	<input type="checkbox"/>
Side Mirrors / Electric	-Select-	<input type="checkbox"/>	Wiper Blades	-Select-	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	SERVICE DUE Km		Dip Stick	Good Condition	<input type="checkbox"/>
Oil Filter	Renewed	<input type="checkbox"/>	Oil Filler Cap	No Visible Leaks	<input type="checkbox"/>
Fuel/Diesel Filter	-Select-	<input type="checkbox"/>	Fan Belt	No Cracks	<input type="checkbox"/>
Air Filter	Within Specification	<input type="checkbox"/>	Fan belt Tensioner	Within Specification	<input type="checkbox"/>
Cabin Filter	Within Specification	<input type="checkbox"/>	Alternator Belt	No Cracks	<input type="checkbox"/>
Spark Plugs	Within Specification	<input type="checkbox"/>	Power Steering Belt	No Cracks	<input type="checkbox"/>
Brake Fluid	No Visible Leaks	<input type="checkbox"/>	Aircon Belt	No Cracks	<input type="checkbox"/>
Antifreeze	No Visible Leaks	<input type="checkbox"/>	Multi V belt	No Cracks	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Within Specification	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Within Specification	<input type="checkbox"/>

Braking System		
Front Brake Pads	80%	<input type="button" value="v"/>
Front Brake Discs	Within Specification	<input type="button" value="v"/>
Front Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Brake Pads	-Select-	<input type="button" value="v"/>
Rear Brake Discs	Not Applicable	<input type="button" value="v"/>
Rear Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Drums	Within Specification	<input type="button" value="v"/>
Rear Linings	60%	<input type="button" value="v"/>
Brake Master	No Visible Leaks	<input type="button" value="v"/>
Hand Brake	Within Specification	<input type="button" value="v"/>
Brake Calipers	Within Specification	<input type="button" value="v"/>
Brake Hose	No Visible Leaks	<input type="button" value="v"/>

Cooling System		
Radiator	No Visible Leaks	<input type="button" value="v"/>
Radiator Hoses	No Visible Leaks	<input type="button" value="v"/>
Waterpump	Within Specification	<input type="button" value="v"/>
Thermostat	Within Specification	<input type="button" value="v"/>
Aircon Gas	No Visible Leaks	<input type="button" value="v"/>
Aircon Pump	Within Specification	<input type="button" value="v"/>
Aircon Condensor	No Visible Leaks	<input type="button" value="v"/>
Interior Fan	Within Specification	<input type="button" value="v"/>
Interior Radiator	No Visible Leaks	<input type="button" value="v"/>

Fueling System		
Intake Manifold	Within Specification	<input type="button" value="v"/>
Throttle	Within Specification	<input type="button" value="v"/>
Turbo	Not Applicable	<input type="button" value="v"/>
Injectors	Within Specification	<input type="button" value="v"/>
Fuel Pump	Within Specification	<input type="button" value="v"/>
Fuel Lines	No Visible Leaks	<input type="button" value="v"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="button" value="v"/>
Glow Plugs	Not Applicable	<input type="button" value="v"/>
Distrubutor	No Fault Code	<input type="button" value="v"/>
HT Leads	No Fault Code	<input type="button" value="v"/>



Steering & Suspension		
Steering Rack	Within Specification	▼
Power Steering Pump	Within Specification	▼
Wheel Alignment	Within Specification	▼
CV Joints	Not Applicable	▼
CV Boots	Not Applicable	▼
Shocks Front	No Visible Leaks	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	No Visible Leaks	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	No Visible Leaks	▼
Propshaft	Within Specification	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Within Specification	▼
Clutch Master	No Visible Leaks	▼
Clutch Slave	No Visible Leaks	▼
Clutch Cable	Not Applicable	▼
Gearbox	Within Specification	▼
Gear & Diff oil	-Select-	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Within Specification	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Code	▼
Cyl Leakage Test	No Visible Leaks	▼
Road Test	Within Specification	▼
Handling	Within Specification	▼

Concluding Remarks

Bosch Technician

Raymond Mncube ▼

General Comments

NEW Technician

Date of Inspection

09-Apr-2024

