



| | | |
|-----------------------|-------------------|---------------------------------|
| Make | TOYOTA | |
| Model | AVANZA 1.3 SX | |
| Vin | MHKM5EA2N0K004229 | |
| Engine Specifications | 1.3 | Petrol <input type="checkbox"/> |
| Vehicle Type | MPV | |
| Service Plan | N/A | |

| | | |
|---------------|-------------------|--------------------------|
| Year | 2017 | |
| Km | 61068 | |
| Transmission | Manual | <input type="checkbox"/> |
| Colour | WHITE | |
| Branch | Bosch Car Service | |
| Warranty Plan | 29/04/2024 | |

Interior

| | | | | | |
|-----------------------|----------------|--------------------------|------------------|----------------|--------------------------|
| Radio / Entertainment | Not Applicable | <input type="checkbox"/> | Aircon Controls | Good Condition | <input type="checkbox"/> |
| Cluster | Good Condition | <input type="checkbox"/> | Electric Windows | Good Condition | <input type="checkbox"/> |

Exterior

| | | | | | |
|-------------------------|----------------|--------------------------|--------------|----------------|--------------------------|
| Windscreen | Good Condition | <input type="checkbox"/> | Mag Wheels | Good Condition | <input type="checkbox"/> |
| Side Mirrors / Electric | Good Condition | <input type="checkbox"/> | Wiper Blades | Good Condition | <input type="checkbox"/> |

BOSCH VEHICLE INSPECTION

Engine

| | | | | | |
|--------------------|----------------|--------------------------|---------------------|----------------|--------------------------|
| Oil Service | | Km | Dip Stick | Good Condition | <input type="checkbox"/> |
| Oil Filter | Good Condition | <input type="checkbox"/> | Oil Filler Cap | Good Condition | <input type="checkbox"/> |
| Fuel/Diesel Filter | Good Condition | <input type="checkbox"/> | Fan Belt | Good Condition | <input type="checkbox"/> |
| Air Filter | Good Condition | <input type="checkbox"/> | Fan belt Tensioner | Good Condition | <input type="checkbox"/> |
| Cabin Filter | Good Condition | <input type="checkbox"/> | Alternator Belt | Good Condition | <input type="checkbox"/> |
| Spark Plugs | Good Condition | <input type="checkbox"/> | Power Steering Belt | Good Condition | <input type="checkbox"/> |
| Brake Fluid | Good Condition | <input type="checkbox"/> | Aircon Belt | Good Condition | <input type="checkbox"/> |
| Antifreeze | Good Condition | <input type="checkbox"/> | Multi V belt | Good Condition | <input type="checkbox"/> |
| Rear Main Seal | Good Condition | <input type="checkbox"/> | Engine Mountings | Good Condition | <input type="checkbox"/> |
| Sump/Gasket | Good Condition | <input type="checkbox"/> | PCV Valve | Good Condition | <input type="checkbox"/> |

| Braking System | | |
|--------------------|----------------|----------------------------------|
| Front Brake Pads | 60% | <input type="button" value="v"/> |
| Front Brake Discs | Good Condition | <input type="button" value="v"/> |
| Front Brake Sensor | Not Applicable | <input type="button" value="v"/> |
| Rear Brake Pads | -Select- | <input type="button" value="v"/> |
| Rear Brake Discs | Not Applicable | <input type="button" value="v"/> |
| Rear Brake Sensor | Not Applicable | <input type="button" value="v"/> |
| Rear Drums | Good Condition | <input type="button" value="v"/> |
| Rear Linings | 60% | <input type="button" value="v"/> |
| Brake Master | Good Condition | <input type="button" value="v"/> |
| Hand Brake | Good Condition | <input type="button" value="v"/> |
| Brake Calipers | Good Condition | <input type="button" value="v"/> |
| Brake Hose | Good Condition | <input type="button" value="v"/> |

| Cooling System | | |
|-------------------|----------------|----------------------------------|
| Radiator | Good Condition | <input type="button" value="v"/> |
| Radiator Hoses | Good Condition | <input type="button" value="v"/> |
| Waterpump | Good Condition | <input type="button" value="v"/> |
| Thermostat | Good Condition | <input type="button" value="v"/> |
| Aircon Gas | Good Condition | <input type="button" value="v"/> |
| Aircon Pump | Good Condition | <input type="button" value="v"/> |
| Aircon Condensor | Good Condition | <input type="button" value="v"/> |
| Interior Fan | Good Condition | <input type="button" value="v"/> |
| Interior Radiator | Good Condition | <input type="button" value="v"/> |

| Fueling System | | |
|-----------------|----------------|----------------------------------|
| Intake Manifold | Good Condition | <input type="button" value="v"/> |
| Throttle | Good Condition | <input type="button" value="v"/> |
| Turbo | Not Applicable | <input type="button" value="v"/> |
| Injectors | Good Condition | <input type="button" value="v"/> |
| Fuel Pump | Good Condition | <input type="button" value="v"/> |
| Fuel Lines | Good Condition | <input type="button" value="v"/> |

| Ignition System | | |
|-----------------|----------------|----------------------------------|
| Ignition Coils | Good Condition | <input type="button" value="v"/> |
| Glow Plugs | Not Applicable | <input type="button" value="v"/> |
| Distrubutor | Not Applicable | <input type="button" value="v"/> |
| HT Leads | Not Applicable | <input type="button" value="v"/> |

| Steering & Suspension | | |
|-----------------------|----------------|----------------------------------|
| Steering Rack | Good Condition | <input type="button" value="v"/> |
| Power Steering Pump | Good Condition | <input type="button" value="v"/> |
| Wheel Alignment | Good Condition | <input type="button" value="v"/> |
| CV Joints | Good Condition | <input type="button" value="v"/> |
| CV Boots | Good Condition | <input type="button" value="v"/> |
| Shocks Front | Good Condition | <input type="button" value="v"/> |
| Shock Mountings Front | Good Condition | <input type="button" value="v"/> |
| Shocks Rear | Good Condition | <input type="button" value="v"/> |
| Stabilizer Links | Good Condition | <input type="button" value="v"/> |
| Wheel Bearings | Good Condition | <input type="button" value="v"/> |
| Bearing Hubs | Good Condition | <input type="button" value="v"/> |
| Control Arms | Good Condition | <input type="button" value="v"/> |
| Sideshafts/Seal | Good Condition | <input type="button" value="v"/> |
| Propshaft | Not Applicable | <input type="button" value="v"/> |
| Wheel Nuts/Studs | Good Condition | <input type="button" value="v"/> |
| Tyres & Spare | -Select- | <input type="button" value="v"/> |
| Mag Wheels/Hub Caps | Good Condition | <input type="button" value="v"/> |

| Transmission & Clutch | | |
|-----------------------|----------------|----------------------------------|
| Clutch Kit | Good Condition | <input type="button" value="v"/> |
| Clutch Master | Good Condition | <input type="button" value="v"/> |
| Clutch Slave | Good Condition | <input type="button" value="v"/> |
| Clutch Cable | Not Applicable | <input type="button" value="v"/> |
| Gearbox | Good Condition | <input type="button" value="v"/> |
| Gear & Diff oil | Good Condition | <input type="button" value="v"/> |
| Auto Transmission | Not Applicable | <input type="button" value="v"/> |
| Gear Selector | Good Condition | <input type="button" value="v"/> |
| Gear Linkages | Good Condition | <input type="button" value="v"/> |

| Ignition System | | |
|------------------|----------|----------------------------------|
| Diagnostics | -Select- | <input type="button" value="v"/> |
| Cyl Leakage Test | -Select- | <input type="button" value="v"/> |
| Road Test | -Select- | <input type="button" value="v"/> |
| Handling | -Select- | <input type="button" value="v"/> |

| Concluding Remarks | |
|--------------------|--|
| | |

| Bosch Technician |
|---|
| -Select- <input type="button" value="v"/> |

| General Comments |
|------------------|
| |

| NEW Technician |
|----------------|
| SHAUN OLIVIER |

| Date of Inspection |
|--------------------|
| |