

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:karika@boschgezina.co.za
Sn:988579800333
Time:2024-04-03 11:33:23
Technician Name:Dries
Customer Name:cittoncars
Order no:
Service fee:
Notes:

Vehicle Information

Year:2019
Make:KIA
Model:RIO(YB)
VIN:KNADB512LK6222641
Displacement:G 1.2 MPI KAPPA
Odometer:136380 km
Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS/ESC
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.AC (Air Conditioning)
- 6.BCM (Body Control Module)
- 7.IC (Instrument Cluster)
- 8.TPMS (Tire Pressure Monitoring System)
- 9.MDPS (Motor Driven Power Steering)
- 10.IMMO (Immobilizer)
- 11.CODE (Transmitter Code Saving)