

ROADWORTHINESS TEST SHEET

Test Number

3705

Licence number and **HFG4P GGA** or not yet allocated and **YGC639W** vehicle register number
 Chassis number/VIN **TSMLYA21800385805**
 Make and series name **SUZUKI VITARA**

NOTE: The figures between brackets refer to the clauses in SANS 10047

01 IDENTIFICATION AND DOCUMENTATION	Fuel system and fuel tank (5.43)	Suspension units (5.44)
Identification - SAPS Clearance (4.4)	Retro-reflectors (5.59)	
Information and registration details (5.2)	Retro-reflective material (5.60)	
	Stairs and passage (6.7, 6.8)	
	Safety design (5.62)	Shock absorbers (5.45)
02 ELECTRICAL SYSTEM	Twist locks for securing containers (5.63)	Stub axles, wheel bearings, control arms and kingpins (5.46)
Windscreen wipers (5.24)	Emergency warning triangle/Emergency exit (6.3)	Stabilizers and anti-roll bars (5.47)
Hooter (5.26)	04 BRAKING SYSTEM	Wheel alignment (5.51) $\psi=10$
Electrical wiring and equipment (5.38)	Brake formula: $1105 \times 4.4 / 1000 = 4.86kN$	Wheel alignment reading
Lamps and lighting (5.58)	Park brake: 12% of brake force = 1.30kN	
	Air or vacuum warning device (5.31)	07 STEERING
	Build-up of air pressure or vacuum (5.32)	Steering wheel (5.28)
	Hand levers for mechanical systems (5.33)	Steering column (5.29)
	Service brake pedal (5.34)	Handlebars and steering (5.30)
	Service brake operation (5.35)	Steering mechanism (5.48)
Flasher type direction indicators (5.61)	Hand-operated air brake valves (5.36)	Power Steering (5.49)
	Braking system - general (5.52)	
03 FITTINGS AND EQUIPMENT	Braking system - specific items (5.53)	
Bumper bars (5.7)	Trailer parking brake (5.54)	08 ENGINE
Wheel flaps (5.8)	Brakes and braking performance (5.55, 5.56)	M1642172164
Trailer coupling on drawing vehicle (5.9)	Service brake	Smoke emission (5.3)
Coupling on trailer (5.10)	L/F 2.3kN R/F 2.7kN	Engine (5.39)
Tilt angle (6.6)	L/R1 1.5kN R/R1 1.4kN	
Coupling socket (5.10)	L/R2 R/R2	Engine and transmission mountings (5.40)
Sides and roof (6.2, 8.2)	L/R3 R/R3	Oil leaks (5.42)
Rear underrun (5.12)	Parking/Emergency brake 2.0kN	
Mudguards (5.13)	L/S1 1.4kN R/S1 1.4kN	09 EXHAUST SYSTEM
Cab mounting (5.14)	L/S2 R/S2	Exhaust system (5.3)
Load body or side car (5.15)	L/S3 R/S3	
Motor cycle fittings (5.16)	05 WHEELS	10 TRANSMISSION AND DRIVE
Safety belts (5.17)	FRONT: RAPID/RAPID 215/55ZR17	Drive train (5.41, 5.50)
Doors (5.18)	Road wheels and hubs (5.4)	
Floor and steps (5.19)	Size and type of tyres (5.5)	
Seats (5.20)	Condition of tyres (5.6)	11 INSTRUMENTS
Mirrors (5.21)	REAR: RAPID/RAPID 215/55ZR17	Speedometer (5.25)
View to front and sides (5.22)	06 SUSPENSION AND UNDERCARRIAGE	12 DIMENSIONS
Windows and windscreen (5.23)	Cleanliness (4.3)	Dimensions (5.57)
Driving controls (5.27)	Chassis or frame (5.37)	
Number of passengers (6.9, 6.11, 8.6) $P5$		
School bus (6.10, 6.11)		

CFR

Pit no. and position in lane	1 and 05	Pit no. and position in lane	
Test date	2:0 2:4 0:4 0:8	Re-test date	2:0 : : :
Time	from 1:30:0 to 1:32:6	Time	from : : : to : : :
Odometer reading	123123	Odometer reading	
Result	Pass	Result	Pass Fail
Testing station infrastructure no.	000007117	Examiner of vehicles infrastructure no.	
Examiner of vehicles infrastructure no.	09813154	Name and signature	
Name and signature	<i>[Signature]</i>	Remarks	
Remarks	PAS3		

APPLICATION FOR CERTIFICATION	AANSOEK OM SERTIFISERING
Fees paid and receipt number for roadworthiness test	Gelde betaal en kwitansienommer van padwaardigheidtoets
R _____ and en _____	

G.P.-S. 02/15
 ACN 71000 + 4 = 1.216
 ACN 71000 + 2 = 1.016
 ACR - 3

REPUBLIC OF SOUTH AFRICA

REPUBLIEK VAN SUID-AFRIKA

**NOTICE IN RESPECT OF
PARTICULARS OF VEHICLE**
(National Road Traffic Act, 1996)

**KENNISGEWING IN VERBAND MET
BESONDERHEDE VAN VOERTUIG**
(Nasionale Padverkeerswet, 1996)

Licence number and vehicle register number	HF64PGGP	and/en	YGK639W	Lisensienommer en voertuigregisternommer	
Date of issue	2024-04-08			Datum van uitreiking	
Infrastructure number of testing station	00000717			Infrastruktuurnommer van toetsstasie	
Infrastructure number and signature of examiner of vehicles	49512HS4	and/en		Infrastruktuurnommer en handtekening van ondersoeker van voertuie	
Chassis number or VIN/ Engine number	TSMLYD21S00385805	/	M16A2172164	Onderstelnummer of VIN/ Enjinnummer	
Make	SUZUKI			Fabrikaat	
Series name	VITARA			Reeksnaam	
Manufacturer's model derivative	6AT GLX			Vervaardiger se modelafgeleide	
Vehicle category	Light passenger mv (less than 12 persons)			Voertuigkategorie	
Driven	Self-propelled / Selfgedrewe			Aandrywing	
Vehicle description on NaTIS	Hatch back / Luikrug			Voertuigbeskrywing op NaVIS	
Vehicle description as seen by Examiner	Hatch back / Luikrug			Voertuigbeskrywing soos deur Ondersoeker gesien	
Net power and engine capacity	86	kW and/en	1586 cm ³	Netto drywing en enjinkapasiteit	
Fuel type	Petrol / Petrol			Tipe brandstof	
Tare (T) and gross vehicle mass (GVM)	1105	kg and/en	1730 kg	Tarra (T) en bruto voertuigmassa (BVM)	
Transmission	Automatic / Outomaties			Transmissie	
Main colour/ Colour change	Other / Ander / N			Hoofkleur/ Kleur verander	
Passenger capacity: seated (incl driver)	5	Passasierskapasiteit: sittend (insl bestuurder)	Passenger capacity: standing	0	Passasierskapasiteit: staande
Gross combination mass (GCM): kg*	2930			Bruto kombinasie-massa (BKM): kg*	
Total number of axles and driving axles	2 and 1 en	Totale aantal asse en aandrywende asse	Total number of wheels	4	Totale aantal wiele
Overall length: mm*	4175	Algehele lengte: mm*	Overall width: mm*	1775	Algehele breedte: mm*
Overall height: mm*	1610	Algehele hoogte: mm*	Rear overhang: mm*	800	Agteroorstek: mm*
Wheelbase: mm*	2500	Asafstand: mm*	Track: mm*	1535	Spoor: mm*
Gearbox number/ Differential number*	/			Ratkasnommer/ Ewenaarnommer*	
Police clearance required	None / Geen			Polisieklaring verlang	
Roadworthy test status	Pass and issued / Slaag en uitgereik			Padwaardigheidtoets status	
Roadworthy status	Roadworthy / Padwaardig			Padwaardigheid status	

NOTE: The certification of the roadworthiness of a motor vehicle cannot in any way be regarded as a guarantee as to the soundness of the construction or mechanical condition of the vehicle concerned.

*Optional

LET WEL: Die sertifisering van die padwaardigheid van 'n motorvoertuig kan geensins beskou word as 'n waarborg dat die konstruksie of meganiese toestand van die betrokke voertuig sonder enige gebrek is nie.

*Opsioneel