

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 2024-04-11 14:54:12
Technician Name: Elias
Order no:
Service fee:
Notes:

Vehicle Information

Make: SUZUKI
VIN: TSMLYD21S00385805
Displacement: G 2.0 MPI NU
Odometer: 0123140 km
Vehicle Software Version: V10.26

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. TCM (Transmission Control Module)
3. ABS (Anti-Lock Braking System)
4. EPS (Electronic Power Steering)
5. AC (Air Conditioning)
6. BCM (Body Control Module)
7. KLS (Keyless Start)
8. IPC (Combination Meter / Meter/ M&A)
9. ALC (Headlight Auto Leveling)