

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:karika@boschgezina.co.za
Sn:988579800333
Time:2024-04-03 13:34:50
Technician Name:Hendrie
Order no:
Service fee:
Notes:

Vehicle Information

Year:2017
Make:VW
Model:vivo
VIN:AAVZZZ6SZHU037952
Displacement:G 1.2 MPI KAPPA
Odometer:0118468 km
Vehicle Software Version:V10.22

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.09 Electronic Central Electric
- 4.15 Airbag
- 5.17 Instrument Cluster
- 6.19 Data Bus OBD Interface
- 7.25 Anti-Theft Immobilizer
- 8.44 Power Steering
- 9.45 Interior Monitoring
- 10.46 Comfort System Central Control Module
- 11.56 Radio