

ROADWORTHINESS TEST SHEET

Test Number

8709

Licence number and **KK6 27TGP** or **not yet allocated** and **JJB576C** vehicle register number
 Chassis number/VIN **AHTBF8JL01016249**
 Make and series name **TOYOTA COROLLA**

NOTE: The figures between brackets refer to the clauses in SANS 10047

01 IDENTIFICATION AND DOCUMENTATION	Fuel system and fuel tank (5.43)	Suspension units (5.44)
Identification - SAPS Clearance (4.4)	Retro-reflectors (5.59)	Retro-reflective material (5.60)
Information and registration details (5.2)	Stairs and passage (6.7, 6.8)	Safety design (5.62)
02 ELECTRICAL SYSTEM	Twist locks for securing containers (5.63)	Emergency warning triangle/Emergency exit (6.3)
Windscreen wipers (5.24)	04 BRAKING SYSTEM	Stabilizers and anti-roll bars (5.47)
Hooter (5.26)	Brake formula: $1230 \times 4.4 / 1000 = 5.41$	Wheel alignment (5.51)
Electrical wiring and equipment (5.38)	Park brake: 12% of brake force = 2.34	Wheel alignment reading 0.50 - F 0.50 - R
Lamps and lighting (5.58)	Air or vacuum warning device (5.31)	07 STEERING
<i>Right side bright not working (no bright made on cluster).</i>	Build-up of air pressure or vacuum (5.32)	Steering wheel (5.28)
<i>Number plate light not working.</i>	Hand levers for mechanical systems (5.33)	Steering column (5.29)
Flasher type direction indicators (5.61)	Service brake pedal (5.34)	Handlebars and steering (5.30)
	Service brake operation (5.35)	Steering mechanism (5.48)
	Hand-operated air brake valves (5.36)	Power Steering (5.49)
03 FITTINGS AND EQUIPMENT	Braking system - general (5.52) <i>B. reservoir cap missing</i>	08 ENGINE 2ZRW882386
Bumper bars (5.7)	Braking system - specific items (5.53)	Smoke emission (5.3)
Wheel flaps (5.8)	Trailer parking brake (5.54)	Engine (5.39)
Trailer coupling on drawing vehicle (5.9)	Brakes and braking performance (5.55, 5.56)	Engine and transmission mountings (5.40)
Coupling on trailer (5.10)	Service brake	Oil leaks (5.42)
Tilt angle (6.6)	L/F 2.7 23 R/F 2.1 25	09 EXHAUST SYSTEM
Coupling socket (5.10)	L/R1 1.4 12 R/R1 1.5 14	Exhaust system (5.3)
Sides and roof (6.2, 8.2)	L/R2 R/R2	10 TRANSMISSION AND DRIVE
Rear underrun (5.12)	L/R3 R/R3	Drive train (5.41, 5.50)
Mudguards (5.13)	Parking/Emergency brake 2.8	11 INSTRUMENTS
Cab mounting (5.14)	L/S1 1.2 13 R/S1 1.3 15	Speedometer (5.25)
Load body or side car (5.15)	L/S2 R/S2	12 DIMENSIONS
Motor cycle fittings (5.16)	L/S3 R/S3	Dimensions (5.57)
Safety belts (5.17)	05 WHEELS Continental x 4	
Doors (5.18)	Road wheels and hubs (5.4)	
Floor and steps (5.19)	Size and type of tyres (5.5) 195/65 R15	
Seats (5.20)	Condition of tyres (5.6)	
Mirrors (5.21)	06 SUSPENSION AND UNDERCARRIAGE	
View to front and sides (5.22)	Cleanliness (4.3)	
Windows and windscreen (5.23)	Chassis or frame (5.37)	
Driving controls (5.27) <i>gear selector not return to the head to position.</i>		
Number of passengers (6.9, 6.11, 8.6) 05		
School bus (6.10, 6.11)		

gear selector not returning

oil leak

Pit no. and position in lane **1** and **04** Pit no. and position in lane **1** and **10**
 Test date **2:0 2:4 0:4 0:9** Re-test date **2:0 2:4 0:4 0:9**
 Time from **10:54** to **1:12:0** Time from **1:44:6** to **1:50:3**
 Odometer reading **RETEST** Odometer reading **60978**
 Result **Pass** Fail Retest **2:0 2:4 0:4 2:3** Result **Pass** Fail
 Testing station infrastructure no. **00000717** Examiner of vehicles infrastructure no. **19520397**
 Examiner of vehicles infrastructure no. **19520397** Name and signature **William A**
 Name and signature **William A** Remarks **- Gear selector return spring does not return to the head to position. - noise coming from big end side when accelerating (loose cover) after selecting reverse. - Both number plate light not working. - Right side bright not working and no display on cluster.**

APPLICATION FOR CERTIFICATION AANSOEK OM SERTIFISERING
 Fees paid and receipt number for roadworthiness test **R 661 AS** and en **130409** Gelde betaal en kwitansienommer van padwaardigheidsstoets

REPUBLIC OF SOUTH AFRICA

REPUBLIEK VAN SUID-AFRIKA

**NOTICE IN RESPECT OF
PARTICULARS OF VEHICLE**

(National Road Traffic Act, 1996)

**KENNISGEWING IN VERBAND MET
BESONDERHEDE VAN VOERTUIG**

(Nasionale Padverkeerswet, 1996)

Licence number and vehicle register number	KK62YTGP	and/en	JJB576L	Lisensienommer en voertuigregisternommer
Date of issue	2024-04-24			Datum van uitreiking
Infrastructure number of testing station	00000717			Infrastruktuurnommer van toetsstasie
Infrastructure number and signature of examiner of vehicles	482103CT	and/en		Infrastruktuurnommer en handtekening van ondersoeker van voertuig
Chassis number or VIN/ Engine number	AHTBF8JEX01016249	/	2ZRW882386	Onderstelnummer of VIN/ Enjinnummer
Make	TOYOTA			Fabriikaat
Series name	COROLLA			Reeksnaam
Manufacturer's model derivative	QUEST 1.8			Vervaardiger se modelafgeleide
Vehicle category	Light passenger mv (less than 12 persons)			Voertuigkategorie
Driven	Self-propelled / Selfgedrewe			Aandrywing
Vehicle description on NaTIS	Sedan (closed top) / Sedan (toe-kap)			Voertuigbeskrywing op NaTIS
Vehicle description as seen by Examiner	Sedan (closed top) / Sedan (toe-kap)			Voertuigbeskrywing soos deur Ondersoeker gesien
Net power and engine capacity	103	kW and/en	1798 cm ³	Netto drywing en enjinkapasiteit
Fuel type	Petrol / Petrol			Tipe brandstof
Tare (T) and gross vehicle mass (GVM)	1230	kg and/en	1785 kg	Tarra (T) en bruto voertuigmassa (BVM)
Transmission	Manual / Hand			Transmissie
Main colour/ Colour change	White / Wit / N			Hoofkleur/ Kleur verander
Passenger capacity: seated (incl driver)	5	Passasierskapasiteit: sittend (insl bestuurder)	Passenger capacity: standing	0 Passasierskapasiteit: staande
Gross combination mass (GCM): kg*	3085			Bruto kombinasie-massa (BKM): kg*
Total number of axles and driving axles	2 and 1 en	Totale aantal asse en aandrywende asse	Total number of wheels	4 Totale aantal wiele
Overall length: mm*	4620	Algehele lengte: mm*	Overall width: mm*	1775 Algehele breedte: mm*
Overall height: mm*	1465	Algehele hoogte: mm*	Rear overhang: mm*	980 Agteroorstek: mm*
Wheelbase: mm*	2700	Asafstand: mm*	Track: mm*	1535 Spoor: mm*
Gearbox number/ Differential number*	/			Ratkasnummer/ Ewenaarnommer*
Police clearance required	None / Geen			Polisieklaring verlang
Roadworthy test status	Pass and issued / Slaag en uitgereik			Padwaardigheidsdoets status
Roadworthy status	Roadworthy / Padwaardig			Padwaardigheid status

NOTE: The certification of the roadworthiness of a motor vehicle cannot in any way be regarded as a guarantee as to the soundness of the construction or mechanical condition of the vehicle concerned.

*Optional

LET WEL: Die sertifisering van die padwaardigheid van 'n motorvoertuig kan geensins beskou word as 'n waarborg dat die konstruksie of meganiese toestand van die betrokke voertuig sonder enige gebrek is nie.

*Opsioneel