

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-04-04 08:33:40
Technician Name:Ricardo
Order no:
Service fee:
Notes:

Vehicle Information

Make:NISSAN
Model:X-Trail
VIN:JN1TCNT32Z0010439
Displacement:G 1.1 SOHC
Odometer:112617 km
Vehicle Software Version:V10.32

Inspection Result

The following systems are OK:

- 1.ENGINE
- 2.ABS
- 3.METER/M&A
- 4.BCM
- 5.AIR BAG
- 6.HVAC
- 7.MULTI AV
- 8.EHS/PKB
- 9.EPS/DAST 3
- 10.IPDM E/R
- 11.AIR PRESSURE MONITOR
- 12.LASER/RADAR
- 13.ALL MODE AWD/4WD
- 14.LANE CAMERA
- 15.CAN GATEWAY
- 16.Side radar (Rear left)
- 17.Side radar (Rear right)
- 18.AVM
- 19.CHASSIS CONTROL
- 20.ICC/ADAS 2
- 21.3ch CAN GATEWAY