

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 12929

Make	MERCEDES-BENZ	
Model	C180 A/T	
Vin	WDD2050402R18735	54
Engine Specifications	1.8	Petrol
Vehicle Type	S/D	
Service Plan	N/A	

Year	2016
Km	88995
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION

Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	-	Fan Belt	No Cracks	-
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	-
Spark Plugs	Within Specification	•	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	•	Aircon Belt	No Cracks	•
Antifreeze	Within Specification	-	Multi V belt	No Cracks	•
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	-
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	-
Thermostat	Within Specification	-
Aircon Gas	Within Specification	-
Aircon Pump	Within Specification	-
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	•
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

WIMPIE

General Comments

Date of Inspection

15-Apr-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

