

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:johan@boschgezina.co.za
Sn:988579800333
Time:2024-04-15 09:01:29
Technician Name:Wimpie F
Order no:
Service fee:
Notes:

Vehicle Information

Make:BENZ
Model:205.040 - C 180 Seda
VIN:WDD2050402R187354
Displacement:G 1.4 DOHC
Odometer:89003 km
Vehicle Software Version:V10.76

Inspection Result

The following systems are OK:

- 1.PTCU - Common Powetrain Controller
- 2.ISM - Intelligent Servo Module
- 3.FSCU - Fuel Pump
- 4.ME - Motor electronics(Engine Control Module - ECM)
- 5.Y3/8 - Transmission control for 9-speed transmission(VGS)
- 6.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 7.B95 (Battery sensor)
- 8.B38/2 (Rain/light sensor with additional functions)
- 9.N70 (Overhead control panel control unit)
- 10.Windshield wiper
- 11.REAR SAM - Rear Signal Acquisition And Actuation Module
- 12.EIS/EZS - Electronic Ignition Lock
- 13.SG-SW_L - Left Headlamp
- 14.SG-SW_R - Right Headlamp
- 15.AB - Supplemental Restraint System
- 16.RevGUS_VL - Left Front Reversible Emergency Tensioning Retractor
- 17.RevGUS_VR - Right Front Reversible Emergency Tensioning Retractor
- 18.SCM - Steering Column Module
- 19.SD - Control Module Sliding Roof
- 20.ATA - Interior Motion Sensor
- 21.LIN bus: AS - Alarm Siren
- 22.Active Brake Assist

- 23.PTS - PARKTRONIC
- 24.TPC - Tire Pressure Monitoring System(TPMS)
- 25.ES - Electrical Power Steering
- 26.ESP - Electronic Stability Program
- 27.COU[ZBE] - Audio/COMAND Operating Unit
- 28.N72/1 (Upper control panel control unit)
- 29.N72/4 (Left lower control panel)
- 30.N72/5 (Right lower control panel)
- 31.ZAN - Audio/COMAND Display
- 32.Audio - Audio Or COMAND
- 33.IC - Instrument Cluster
- 34.AC - Air Conditioning
- 35.DCU-LF - Left Front Door
- 36.DCU_RF - Right Front Door
- 37.DCU-LR - Left Rear Door
- 38.DCU-RR - Right Rear Door