Make	FORD		
Model	ECOSPORT 1.5TiVCT TITANIUM P/SHIFT		
Vin	MAJAXXMRKAEJ68045		
Engine Specifications	1.5	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2014
Km	154598
Transmission	Manual
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	-
Cluster	Within Specification	—	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	~
Side Mirrors / Electric	Within Specification	—	Wiper Blades	Renewed	~

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks	-
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	-
Spark Plugs	Within Specification		Power Steering Belt	No Cracks	-
Brake Fluid	Within Specification		Aircon Belt	No Cracks	-
Antifreeze	Within Specification		Multi V belt	No Cracks	-
Rear Main Seal	No Visible Leaks ▼		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	—
Radiator Hoses	No Visible Leaks	lacksquare
Waterpump	Within Specification	-
Thermostat	No Visible Leaks	-
Aircon Gas	Within Specification	~
Aircon Pump	No Visible Leaks	—
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	V
Turbo	Not Applicable	•
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	~
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	-
CV Joints	Within Specification	•
CV Boots	Within Specification	-
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	lacksquare
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	-
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	-
Auto Transmission	Within Specification	-
Gear Selector	Within Specification	
Gear Linkages	Not Applicable	V

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Bosch Technician	General Comments
Luandre Swanepoel	
NEW Technician	Date of Inspection
	- Bate of inspection



Concluding Remarks

