

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 13058

Make	MAHINDRA		
Model	XUV 500 2.2D MHAWK A/T (W6) 7 SEAT		
Vin	MA1YV2VMVN6078352		
Engine Specifications	2.2	Diesel	
Vehicle Type	SUV		
Service Plan	26/05/2027		

Year	2022
Km	46686
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	26/05/2027

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Good Condition	-	Electric Windows	Working Condition	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Renewed	-

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification	-
Oil Filter	Renewed	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	No Visible Leaks	Fan Belt	No Cracks	•
Air Filter	Within Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	Power Steering Belt	No Cracks	•
Brake Fluid	No Visible Leaks	Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification	-
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification	•



Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	-
Rear Brake Pads	40%	•
Rear Brake Discs	Within Specification	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	-
Rear Linings	-Select-	-
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	-
Brake Calipers	No Visible Leaks	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	-
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Within Specification	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	No Visible Leaks	-
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

Raymond Mncube

NEW Technician

General Comments

Date of Inspection

17-Apr-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

