Make	HYUNDAI		
Model	H100 2.6D A/C F/C D/S		
Vin	KMFZBX7BLHU45772	29	
Engine Specifications	2.6	Diesel	
Vehicle Type	D/S		
Service Plan	N/A		

Year	2018
Km	206420
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	~	Aircon Controls	Within Specification	•
Cluster	Working Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Renewed	~	Mag Wheels	Not Applicable	V
Side Mirrors / Electric	Within Specification	—	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		206424 Km	Dip Stick	Within Specification	•
Oil Filter	Renewed	~	Oil Filler Cap	No Visible Leaks	~
Fuel/Diesel Filter	No Visible Leaks	~	Fan Belt	No Cracks	•
Air Filter	Within Specification	—	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	_	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	—	Power Steering Belt	No Cracks	•
Brake Fluid	No Visible Leaks	~	Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks	lacksquare	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	~	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	\rightarrow	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	_
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Renewed	
Aircon Pump	Within Specification	_
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	_
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	~
Power Steering Pump	Within Specification	•
Wheel Alignment	Renewed	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Renewed	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	—
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	No Visible Leaks	
Clutch Slave	No Visible Leaks	
Clutch Cable	Not Applicable	
Gearbox	Within Specification	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding hemarks	
Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection
	25-Apr-2024



