Make	NISSAN		
Model	NP200 1.5 DCi A/C SAFETY PACK P/U S/C		
Vin	ADNUSN365U0101311		
Engine Specifications	1.5 Petrol		
Vehicle Type	S/C		
Service Plan	N/A		

Year	2015
Km	95028
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	—	Aircon Controls	Good Condition	•
Cluster	Good Condition	V	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	-Select-	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		95028 Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	lacksquare	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	lacksquare	Fan Belt	Good Condition	V
Air Filter	Good Condition	—	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	_	Alternator Belt	Good Condition	•
Spark Plugs	Not Applicable		Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	_	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	—	Multi V belt	Good Condition	•
Rear Main Seal	No Visible Leaks	—	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	lacksquare
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	100%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	—
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	—
Throttle	Good Condition	lacksquare
Turbo	Good Condition	lacksquare
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Good Condition	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	—
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	lacksquare
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	
Wheel Nuts/Studs	Good Condition	
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	lacksquare

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	lacksquare
Clutch Cable	Good Condition	V
Gearbox	Good Condition	V
Gear & Diff oil	Good Condition	V
Auto Transmission	Not Applicable	lacksquare
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	V

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	~

Concluding Remarks	
Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



