Make	HYUNDAI		
Model	i10 1.1 GLS/MOTION		
Vin	MALAN51BLEM5379	21	
Engine Specifications	1.1	Petrol	▼
Vehicle Type	H/B		

Year	2014
Km	94859
Transmission	Manual
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	•
Cluster	Within Specification	-	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		84982 Km	Dip Stick	Within Specification	-
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	—	Fan Belt	Not Applicable	•
Air Filter	Within Specification	—	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	_	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	_	Power Steering Belt	Not Applicable	-
Brake Fluid	Within Specification	_	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	lacksquare	Multi V belt	No Cracks	•
Rear Main Seal	No Fault Code	—	Engine Mountings	Within Specification	•
Sump/Gasket	No Fault Code	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	
Rear Linings	60%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	~
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	V
Turbo	Not Applicable	•
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	~
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Within Specification	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	—
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Renewed	•
CV Boots	Renewed	•
Shocks Front	Within Specification	—
Shock Mountings Front	Within Specification	—
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	—
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	Within Specification	
Clutch Slave	Within Specification	
Clutch Cable	Within Specification	
Gearbox	Within Specification	
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Bosch Technician		General Comments
Eugene J.v. Rensburg	•	

NEW Technician	Date of Inspection



Concluding Remarks

