

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:jaco@boschgezina.co.za
Sn:988579800333
Time:2024-04-25 07:44:43
Technician Name:Eugene
Order no:
Service fee:
Notes:

Vehicle Information

Make:SMART
Model:smart 453
VIN:WME4530422Y074901
Odometer:111300 km
Vehicle Software Version:V10.10

Inspection Result

The following systems are OK:

- 1.ME - Motor electronics(ME17_453)
- 2.ESP - Electronic Stability Program
- 3.Driver-side SAM - Signal Acquisition And Actuation Module (N10/11)
- 4.SAM-M - Signal Acquisition And Actuation Module (N10/10)
- 5.AGW - Audio Gateway
- 6.IC - Instrument Cluster (A1)
- 7.AAC - Air Conditioning