

Year	2016
Km	139829
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	—	Aircon Controls	Good Condition	T
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Renewed	-	Mag Wheels	-Select-	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		139829 Km	Dip Stick	Good Condition	•
Oil Filter	Renewed	—	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Not Applicable	lacksquare	Fan Belt	Renewed	V
Air Filter	Within Specification		Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	—	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	•
Brake Fluid	Good Condition	_	Aircon Belt	Not Applicable	-
Antifreeze	Good Condition	—	Multi V belt	Renewed	~
Rear Main Seal	No Visible Leaks	—	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	lacksquare
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	lacksquare
Rear Linings	60%	•
Brake Master	Good Condition	lacksquare
Hand Brake	Good Condition	lacksquare
Brake Calipers	Good Condition	lacksquare
Brake Hose	Good Condition	lacksquare

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	-
Thermostat	No Visible Leaks	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	~

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	Within Specification	-
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	—
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	—
HT Leads	Within Specification	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Renewed	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	T
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	—

Transmission & Clutch				
Clutch Kit	Within Specification	•		
Clutch Master	No Visible Leaks	•		
Clutch Slave	Not Applicable	•		
Clutch Cable	Good Condition	•		
Gearbox	Good Condition	•		
Gear & Diff oil	Good Condition	•		
Auto Transmission	Not Applicable	•		
Gear Selector	Good Condition	•		
Gear Linkages	Good Condition	T		

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	-
Handling	Good Condition	▼

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
HENDRE	17-Apr-2024



