

Make	FORD	
Model	ECOSPORT 1.0 ECOBOOST TREND A/T	
Vin	WF01XXERK1JY36950	
Engine Specifications	1.0	Petrol <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2018	
Km	141393	
Transmission	Manual	<input type="checkbox"/>
Colour	WHITE	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Good Condition	<input type="checkbox"/>	Aircon Controls	Good Condition	<input type="checkbox"/>
Cluster	Good Condition	<input type="checkbox"/>	Electric Windows	Good Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Good Condition	<input type="checkbox"/>	Wiper Blades	Renewed	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		Km	Dip Stick	No Visible Leaks	<input type="checkbox"/>
Oil Filter	Good Condition	<input type="checkbox"/>	Oil Filler Cap	No Visible Leaks	<input type="checkbox"/>
Fuel/Diesel Filter	Not Applicable	<input type="checkbox"/>	Fan Belt	Not Applicable	<input type="checkbox"/>
Air Filter	Good Condition	<input type="checkbox"/>	Fan belt Tensioner	Good Condition	<input type="checkbox"/>
Cabin Filter	Good Condition	<input type="checkbox"/>	Alternator Belt	No Visible Leaks	<input type="checkbox"/>
Spark Plugs	Good Condition	<input type="checkbox"/>	Power Steering Belt	No Visible Leaks	<input type="checkbox"/>
Brake Fluid	Good Condition	<input type="checkbox"/>	Aircon Belt	No Visible Leaks	<input type="checkbox"/>
Antifreeze	Good Condition	<input type="checkbox"/>	Multi V belt	No Visible Leaks	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Good Condition	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Good Condition	<input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="checkbox"/>
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	-Select-	<input type="checkbox"/>
Rear Brake Discs	Not Applicable	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Within Specification	<input type="checkbox"/>
Rear Linings	60%	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	Good Condition	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	Within Specification	<input type="checkbox"/>
Aircon Pump	Good Condition	<input type="checkbox"/>
Aircon Condensor	Good Condition	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	Good Condition	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Good Condition	<input type="checkbox"/>
Injectors	Good Condition	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	Good Condition	<input type="checkbox"/>

Ignition System		
Ignition Coils	Good Condition	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distrubutor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	<input type="button" value="v"/>
Power Steering Pump	Good Condition	<input type="button" value="v"/>
Wheel Alignment	Renewed	<input type="button" value="v"/>
CV Joints	Good Condition	<input type="button" value="v"/>
CV Boots	Good Condition	<input type="button" value="v"/>
Shocks Front	Good Condition	<input type="button" value="v"/>
Shock Mountings Front	Good Condition	<input type="button" value="v"/>
Shocks Rear	Good Condition	<input type="button" value="v"/>
Stabilizer Links	Good Condition	<input type="button" value="v"/>
Wheel Bearings	Good Condition	<input type="button" value="v"/>
Bearing Hubs	Good Condition	<input type="button" value="v"/>
Control Arms	Good Condition	<input type="button" value="v"/>
Sideshafts/Seal	Good Condition	<input type="button" value="v"/>
Propshaft	Not Applicable	<input type="button" value="v"/>
Wheel Nuts/Studs	Good Condition	<input type="button" value="v"/>
Tyres & Spare	Renewed	<input type="button" value="v"/>
Mag Wheels/Hub Caps	Good Condition	<input type="button" value="v"/>

Transmission & Clutch		
Clutch Kit	Not Applicable	<input type="button" value="v"/>
Clutch Master	Not Applicable	<input type="button" value="v"/>
Clutch Slave	Not Applicable	<input type="button" value="v"/>
Clutch Cable	Not Applicable	<input type="button" value="v"/>
Gearbox	Not Applicable	<input type="button" value="v"/>
Gear & Diff oil	Good Condition	<input type="button" value="v"/>
Auto Transmission	Good Condition	<input type="button" value="v"/>
Gear Selector	Good Condition	<input type="button" value="v"/>
Gear Linkages	Good Condition	<input type="button" value="v"/>

Ignition System		
Diagnostics	No Fault Code	<input type="button" value="v"/>
Cyl Leakage Test	No Visible Leaks	<input type="button" value="v"/>
Road Test	Good Condition	<input type="button" value="v"/>
Handling	Good Condition	<input type="button" value="v"/>

Concluding Remarks	

Bosch Technician	
-Select- <input type="button" value="v"/>	

General Comments	

NEW Technician	
HENDRE NIEMAND	

Date of Inspection	
18-Apr-2024	