Make	FIAT		
Model	500X 1.4T CROSS DDCT		
Vin	ZFA3340000P43267	2	
Engine Specifications			1
Engine Specifications	1.4	Petrol	
Vehicle Type	1.4 H/B	Petrol	1

Year	2016
Km	89405
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	_	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	<b>—</b>	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	No Fault Code	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	24-11-2023 Km		Dip Stick	Within Specification	•
Oil Filter	No Visible Leaks		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code   ▼		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks   ▼		Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks  ▼		Multi V belt	No Cracks	<b>~</b>
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	<b>V</b>
Sump/Gasket	No Visible Leaks   ▼		PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	No Fault Code	
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	No Fault Code	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	
Brake Master	No Visible Leaks	•
Hand Brake	No Fault Code	
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	<b>~</b>
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	lacksquare
Distrubutor	Not Applicable	_
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	No Visible Leaks	•
Power Steering Pump	Not Applicable	<b>—</b>
Wheel Alignment	Within Specification	
CV Joints	No Visible Leaks	<b>—</b>
CV Boots	No Visible Leaks	
Shocks Front	No Visible Leaks	<b>V</b>
Shock Mountings Front	Within Specification	<b>—</b>
Shocks Rear	No Visible Leaks	
Stabilizer Links	Within Specification	lacksquare
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	lacksquare
Sideshafts/Seal	No Visible Leaks	lacksquare
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Within Specification	-
Tyres & Spare	Within Specification	<b>—</b>
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	<b>T</b>
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	No Visible Leaks	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	<b>~</b>
Road Test	Within Specification	-
Handling	Within Specification	<b>T</b>

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



