

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:jaco@boschgezina.co.za
Sn:988579800333
Time:2024-04-24 16:02:12
Technician Name:Dries
Customer Name:cittoncars
Order no:
Service fee:
Notes:

Vehicle Information

Make:FIAT
VIN:ZFA3340000P432672
Odometer:89408 km
Vehicle Software Version:V10.72

Inspection Result

The following systems are OK:

- 1.BCM (Body Control Module)
- 2.IPC (Instrument Panel Cluster)
- 3.ESM (Electronic Shifter)
- 4.ECM (Engine Control Module)
- 5.TCM (Transmission Control Module)
- 6.ABS (Anti-Lock Braking System)
- 7.ORB (Occupant Restraint)
- 8.PAM (Parking Assistant Module)
- 9.EPS (Electric Power Steering)
- 10.ETM (Entertainment Telematic Module)
- 11.HVAC (Heating Ventilation Air-Conditioning And Cooling)