

| | | |
|-----------------------|-----------------------|---------------------------------|
| Make | MAHINDRA | |
| Model | KUV 100 1.2 K2+ #DARE | |
| Vin | MA1VC2RBCL6085200 | |
| Engine Specifications | 1.2 | Petrol <input type="checkbox"/> |
| Vehicle Type | SUV | |
| Service Plan | N/A | |

| | | |
|---------------|-------------------|--------------------------|
| Year | 2019 | |
| Km | 116585 | |
| Transmission | Manual | <input type="checkbox"/> |
| Colour | WHITE | |
| Branch | Bosch Car Service | |
| Warranty Plan | N/A | |

Interior

| | | | | | |
|-----------------------|---------------|--------------------------|------------------|----------------|--------------------------|
| Radio / Entertainment | No Fault Code | <input type="checkbox"/> | Aircon Controls | No Fault Code | <input type="checkbox"/> |
| Cluster | No Fault Code | <input type="checkbox"/> | Electric Windows | Not Applicable | <input type="checkbox"/> |

Exterior

| | | | | | |
|-------------------------|----------------------|--------------------------|--------------|----------------------|--------------------------|
| Windscreen | Within Specification | <input type="checkbox"/> | Mag Wheels | Within Specification | <input type="checkbox"/> |
| Side Mirrors / Electric | Within Specification | <input type="checkbox"/> | Wiper Blades | Renewed | <input type="checkbox"/> |

BOSCH VEHICLE INSPECTION

Engine

| | | | | | |
|--------------------|----------------------|--------------------------|---------------------|----------------------|--------------------------|
| Oil Service | SERVICE DUE Km | | Dip Stick | Within Specification | <input type="checkbox"/> |
| Oil Filter | Good Condition | <input type="checkbox"/> | Oil Filler Cap | Within Specification | <input type="checkbox"/> |
| Fuel/Diesel Filter | Not Applicable | <input type="checkbox"/> | Fan Belt | No Cracks | <input type="checkbox"/> |
| Air Filter | Within Specification | <input type="checkbox"/> | Fan belt Tensioner | Within Specification | <input type="checkbox"/> |
| Cabin Filter | Within Specification | <input type="checkbox"/> | Alternator Belt | No Cracks | <input type="checkbox"/> |
| Spark Plugs | No Fault Code | <input type="checkbox"/> | Power Steering Belt | Not Applicable | <input type="checkbox"/> |
| Brake Fluid | No Visible Leaks | <input type="checkbox"/> | Aircon Belt | No Cracks | <input type="checkbox"/> |
| Antifreeze | No Visible Leaks | <input type="checkbox"/> | Multi V belt | No Cracks | <input type="checkbox"/> |
| Rear Main Seal | No Visible Leaks | <input type="checkbox"/> | Engine Mountings | Within Specification | <input type="checkbox"/> |
| Sump/Gasket | No Visible Leaks | <input type="checkbox"/> | PCV Valve | No Visible Leaks | <input type="checkbox"/> |

| Braking System | | |
|--------------------|----------------------|--------------------------|
| Front Brake Pads | 40% | <input type="checkbox"/> |
| Front Brake Discs | Within Specification | <input type="checkbox"/> |
| Front Brake Sensor | Not Applicable | <input type="checkbox"/> |
| Rear Brake Pads | -Select- | |
| Rear Brake Discs | Not Applicable | <input type="checkbox"/> |
| Rear Brake Sensor | Not Applicable | <input type="checkbox"/> |
| Rear Drums | Within Specification | <input type="checkbox"/> |
| Rear Linings | 60% | <input type="checkbox"/> |
| Brake Master | No Visible Leaks | <input type="checkbox"/> |
| Hand Brake | Within Specification | <input type="checkbox"/> |
| Brake Calipers | No Visible Leaks | <input type="checkbox"/> |
| Brake Hose | No Visible Leaks | <input type="checkbox"/> |

| Cooling System | | |
|-------------------|------------------|--------------------------|
| Radiator | No Visible Leaks | <input type="checkbox"/> |
| Radiator Hoses | No Visible Leaks | <input type="checkbox"/> |
| Waterpump | No Visible Leaks | <input type="checkbox"/> |
| Thermostat | No Visible Leaks | <input type="checkbox"/> |
| Aircon Gas | No Visible Leaks | <input type="checkbox"/> |
| Aircon Pump | No Fault Code | <input type="checkbox"/> |
| Aircon Condensor | No Visible Leaks | <input type="checkbox"/> |
| Interior Fan | No Fault Code | <input type="checkbox"/> |
| Interior Radiator | No Visible Leaks | <input type="checkbox"/> |

| Fueling System | | |
|-----------------|------------------|--------------------------|
| Intake Manifold | No Visible Leaks | <input type="checkbox"/> |
| Throttle | No Fault Code | <input type="checkbox"/> |
| Turbo | Not Applicable | <input type="checkbox"/> |
| Injectors | No Fault Code | <input type="checkbox"/> |
| Fuel Pump | No Fault Code | <input type="checkbox"/> |
| Fuel Lines | No Visible Leaks | <input type="checkbox"/> |

| Ignition System | | |
|-----------------|----------------|--------------------------|
| Ignition Coils | No Fault Code | <input type="checkbox"/> |
| Glow Plugs | Not Applicable | <input type="checkbox"/> |
| Distributor | Not Applicable | <input type="checkbox"/> |
| HT Leads | Not Applicable | <input type="checkbox"/> |

| Steering & Suspension | | |
|-----------------------|----------------------|--------------------------|
| Steering Rack | No Visible Leaks | <input type="checkbox"/> |
| Power Steering Pump | Not Applicable | <input type="checkbox"/> |
| Wheel Alignment | Renewed | <input type="checkbox"/> |
| CV Joints | No Visible Leaks | <input type="checkbox"/> |
| CV Boots | No Visible Leaks | <input type="checkbox"/> |
| Shocks Front | No Visible Leaks | <input type="checkbox"/> |
| Shock Mountings Front | Within Specification | <input type="checkbox"/> |
| Shocks Rear | No Visible Leaks | <input type="checkbox"/> |
| Stabilizer Links | Good Condition | <input type="checkbox"/> |
| Wheel Bearings | Within Specification | <input type="checkbox"/> |
| Bearing Hubs | Within Specification | <input type="checkbox"/> |
| Control Arms | Within Specification | <input type="checkbox"/> |
| Sideshafts/Seal | No Visible Leaks | <input type="checkbox"/> |
| Propshaft | Not Applicable | <input type="checkbox"/> |
| Wheel Nuts/Studs | Within Specification | <input type="checkbox"/> |
| Tyres & Spare | Within Specification | <input type="checkbox"/> |
| Mag Wheels/Hub Caps | Within Specification | <input type="checkbox"/> |

| Transmission & Clutch | | |
|-----------------------|----------------------|--------------------------|
| Clutch Kit | Good Condition | <input type="checkbox"/> |
| Clutch Master | No Visible Leaks | <input type="checkbox"/> |
| Clutch Slave | No Visible Leaks | <input type="checkbox"/> |
| Clutch Cable | Not Applicable | <input type="checkbox"/> |
| Gearbox | No Visible Leaks | <input type="checkbox"/> |
| Gear & Diff oil | No Visible Leaks | <input type="checkbox"/> |
| Auto Transmission | Not Applicable | <input type="checkbox"/> |
| Gear Selector | Within Specification | <input type="checkbox"/> |
| Gear Linkages | Within Specification | <input type="checkbox"/> |

| Ignition System | | |
|------------------|----------------------|--------------------------|
| Diagnostics | No Fault Code | <input type="checkbox"/> |
| Cyl Leakage Test | No Visible Leaks | <input type="checkbox"/> |
| Road Test | Within Specification | <input type="checkbox"/> |
| Handling | Within Specification | <input type="checkbox"/> |

Concluding Remarks

Bosch Technician

Dries Olwagan

General Comments

NEW Technician

Date of Inspection