Make	ISUZU		
Model	KB 250 D-TEQ HO X-RIDER 4X4 P/U /D/C		
Vin	ADMLSCHR3H48211	30	
Engine Specifications	2.5	Petrol	
Vehicle Type	D/C		
Service Plan	N/A		

Year	2017
Km	111679
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Working Condition	-	Electric Windows	Working Condition	V

Exterior					
Windscreen	Renewed	•	Mag Wheels	Within Specification	~
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Good Condition	~

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		111098 Km	Dip Stick	Good Condition	•
Oil Filter	Within Specification	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	No Visible Leaks	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	~	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	•	Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	•	Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks	•	Multi V belt	No Cracks	T
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	V	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	lacksquare
Rear Drums	Within Specification	lacksquare
Rear Linings	60%	lacksquare
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	lacksquare
Radiator Hoses	No Visible Leaks	lacksquare
Waterpump	Within Specification	•
Thermostat	Within Specification	-
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	Within Specification	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	—
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	lacksquare
Stabilizer Links	Within Specification	V
Wheel Bearings	Within Specification	V
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	—
Sideshafts/Seal	No Visible Leaks	V
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	lacksquare
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	—
Clutch Cable	Not Applicable	T
Gearbox	Within Specification	T
Gear & Diff oil	No Visible Leaks	—
Auto Transmission	Not Applicable	—
Gear Selector	Good Condition	T
Gear Linkages	Within Specification	v

Ignition System		
Diagnostics	-Select-	•
Cyl Leakage Test	No Visible Leaks	~
Road Test	Within Specification	-
Handling	Within Specification	•

Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection



Concluding Remarks



30-Apr-2024