Make	SUBARU	
Model	IMPREZA 2.0i CVT	
Vin	JF1GK7KL5JG007589	1
Engine Specifications	2.0	Datas
Engine opecinications	2.0	Petrol
Vehicle Type	S/D	Petrol

Year	2018
Km	96044
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	-
Cluster	Within Specification	•	Electric Windows	Within Specification	<b>•</b>

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	<b>—</b>
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE	Km	Dip Stick	No Visible Leaks	•
Oil Filter	Within Specification	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	<b>—</b>	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	<b>~</b>	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	<b>~</b>
Brake Fluid	Within Specification	<b>~</b>	Aircon Belt	No Cracks	<b>~</b>
Antifreeze	Within Specification	•	Multi V belt	No Cracks	<b>~</b>
Rear Main Seal	No Visible Leaks	<b>—</b>	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	No Visible Leaks	•
Aircon Gas	Within Specification	<b>—</b>
Aircon Pump	Within Specification	<b>V</b>
Aircon Condensor	No Visible Leaks	<b>~</b>
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	<b>V</b>

Fueling System		
Intake Manifold	Within Specification	<b>V</b>
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>—</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>~</b>
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	<b>—</b>
Clutch Cable	Not Applicable	<b>T</b>
Gearbox	Within Specification	<b>T</b>
Gear & Diff oil	Within Specification	<b>—</b>
Auto Transmission	Within Specification	<b>—</b>
Gear Selector	Within Specification	<b>T</b>
Gear Linkages	Not Applicable	<b>v</b>

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	<b>T</b>

Concluding Remarks	
Bosch Technician	General Comments
Luandre Swanepoel	
NEW Technician	Date of Inspection



