

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 13306

Make	HONDA		
Model	BALLADE 1.5 ELEGANCE CVT		
Vin	MAKGM66G0F4000093		
Engine Specifications	1.5 Petr	rol	
Vehicle Type	S/D		
Service Plan	N/A		

Year	2016
Km	116152
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	<b>•</b>

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Good Condition	•

## **BOSCH VEHICLE INSPECTION**

Oil Service		114081 Km	Dip Stick	Within Specification	,
Oil Filter	Within Specification	-	Oil Filler Cap	Within Specification	
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	-
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	,
Brake Fluid	Good Condition	•	Aircon Belt	No Cracks	,
Antifreeze	Good Condition	•	Multi V belt	No Cracks	,
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	-
Sump/Gasket	-Select-	•	PCV Valve	Within Specification	r

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	60%	-
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	-
Rear Linings	60%	•
Brake Master	Within Specification	-
Hand Brake	Within Specification	•
Brake Calipers	-Select-	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	Within Specification	-
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 13306

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	-Select-	•
Mag Wheels/Hub Caps	-Select-	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	-

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

**RIAAN MEINTJIES** 

-Select-

## General Comments

Date of Inspection

30-Apr-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

