Make	CHEVROLET		
Model	UTILITY 1.4 A/C P/U S/C		
Vin	ADMJF4MRXF	4735401	
Engine Specifications	1.4	Petrol	V
Vehicle Type	S/C		
Service Plan	N/A		

Year	2015
Km	72956
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	V	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	Renewed	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	Renewed	•
Spark Plugs	Within Specification		Power Steering Belt	Renewed	•
Brake Fluid	Good Condition		Aircon Belt	Renewed	-
Antifreeze	Good Condition		Multi V belt	Renewed	_
Rear Main Seal	No Visible Leaks		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	—
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	—
Brake Hose	No Visible Leaks	—

Cooling System		
Radiator	No Visible Leaks	_
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	Within Specification	_
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	-
Interior Radiator	No Visible Leaks	V

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	~
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Within Specification	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Within Specification	lacksquare
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	-Select-	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	-Select-	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Within Specification	-
Clutch Master	Within Specification	-
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	-
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	-
Auto Transmission	Not Applicable	-
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	_
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	-
Handling	Good Condition	•

Concluding Remarks		

Bosch Technician		General Comments
-Select-	¥	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	06-May-2024



