Make	TOYOTA		
Model	COROLLA QUEST 1.6 A/T		
Vin	AHTLB52E70314640	09	
Engine Specifications	1.6	Petrol	
Vehicle Type	S/D		
Service Plan	N/A		

Year	2019
Km	65443
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	~	Aircon Controls	Within Specification	_
Cluster	Within Specification	—	Electric Windows	Within Specification	_

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	—
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		65448 Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	_	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	lacksquare	Fan Belt	Within Specification	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	_	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification		Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	_	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	-	Multi V belt	Within Specification	•
Rear Main Seal	Within Specification	_	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	—
Front Brake Discs	Within Specification	•
Front Brake Sensor	-Select-	
Rear Brake Pads	-Select-	
Rear Brake Discs	-Select-	
Rear Brake Sensor	-Select-	
Rear Drums	Within Specification	—
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	—
Brake Hose	Within Specification	—

Cooling System		
Radiator	Within Specification	
Radiator Hoses	Within Specification	lacksquare
Waterpump	Within Specification	—
Thermostat	Within Specification	•
Aircon Gas	Within Specification	—
Aircon Pump	Within Specification	lacksquare
Aircon Condensor	Within Specification	V
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	lacksquare

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Within Specification	•
Distrubutor	-Select-	
HT Leads	-Select-	



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	V
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	lacksquare
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	lacksquare
Wheel Bearings	Within Specification	lacksquare
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	lacksquare
Sideshafts/Seal	Within Specification	lacksquare
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	-Select-	
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	—
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	-

Ignition System		
Diagnostics	Within Specification	V
Cyl Leakage Test	Within Specification	~
Road Test	Within Specification	~
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection
	08-May-2024



