

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-05-08 08:32:48
Technician Name:Ricardo
Order no:
Service fee:
Notes:

Vehicle Information

Year:2008
Make:TOYOTA
Model:Corolla
VIN:AHTLB52E703146409
Displacement:G 1.1 SOHC
Odometer:65448.00 km
Vehicle Software Version:V10.44

Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.CCS (Cruise Control)
- 4.SRS (Supplemental Inflatable Restraint System)
- 5.AC (Air Conditioning)
- 6.BCM (Body Control Module)
- 7.DDM (Driver Door Motor)
- 8.IMMO (Immobiliser)