
Make	JEEP	
Model	RENEGADE 1.4 TJET LTD AWD A/T 75TH	
Vin	1C4BU0000GPD79306	
Engine Specifications	1.4	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2016
Km	109814
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	—	Aircon Controls	Good Condition	T
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	-	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	-	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	~	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	-	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•



Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	lacksquare
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	-Select-	
Glow Plugs	-Select-	•
Distrubutor	-Select-	
HT Leads	-Select-	



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	—
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	V
CV Joints	Good Condition	V
CV Boots	Good Condition	V
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	V
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	V
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	lacksquare
Sideshafts/Seal	Good Condition	V
Propshaft	Good Condition	V
Wheel Nuts/Studs	Good Condition	v
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	-Select-	•
Clutch Master	-Select-	•
Clutch Slave	-Select-	—
Clutch Cable	-Select-	
Gearbox	-Select-	T
Gear & Diff oil	-Select-	—
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	-Select-	•

Ignition System		
Diagnostics	-Select-	V
Cyl Leakage Test	-Select-	~
Road Test	-Select-	~
Handling	-Select-	~

Bosch Technician -Select-	General Comments
NEW Technician	Date of Inspection



Concluding Remarks

