

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-05-08 07:42:54
Technician Name:shaun
Order no:
Service fee:
Notes:

Vehicle Information

Year:2016
Make:CHRYSLER
Model:Renegade(BU)
VIN:1C4BU0000GPD79306
Displacement:G 1.1 SOHC
Odometer:109822 km
Vehicle Software Version:V10.50

Inspection Result

The following systems are OK:

- 1.PCM (Powertrain Control Module)
- 2.TCM (Transmission Control Module)
- 3.BCM (Body Control Module - TIPMCGW/FCMCGW)
- 4.IPC (Instrument Panel Cluster)
- 5.RFH/TPMS (Radio Frequency Hub - Tire)
- 6.ACC (Adaptive Cruise Control)
- 7.ESM (Electronic Shifter Module)
- 8.DTCM (Drive Train Control Module)
- 9.ABS (Anti-lock Braking System)
- 10.SRS (Supplemental Inflatable Restraint System - ORC (Occupant Restraint Controller))
- 11.HALF (Haptical Lane Feedback)
- 12.PAM (Park Assist Module)
- 13.EPS (Electronic Power Steering)
- 14.HVAC (Heating Ventilation Air-conditioning And Cooling)/AC (Air Conditioner)
- 15.RBSS (Right Blind Spot Sensor)
- 16.LBSS (Left Blind Spot Sensor)
- 17.ETM (Entertainment Telematic Module)