

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: citton cars  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: lukas@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-05-08 07:38:49  
Technician Name: Riaan  
Customer Name: citton cars  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year: 2016  
Make: MAZDA  
Model: CX-5  
VIN: JM6KE1072G0359177  
Displacement: G 1.1 SOHC  
Odometer: 93687 km  
Vehicle Software Version: V10.28

## Inspection Result

The following systems are OK:

- 1.F\_BCM (Front Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.R\_BCM (Rear Body Control Module)
- 5.RCM (Restraint Control Module)
- 6.TCM (Transmission Control Module)
- 7.ABS (Anti-Lock Brake System)
- 8.EATC#1 (Electronic Air Temperature Controller)
- 9.CMU (Connectivity Master Unit)
- 10.EPB (Electrical Parking Brake)
- 11.EPS (Electronic Power Steering)
- 12.SSU#1 (Start Stop Unit)