

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 13398

Make	NISSAN	
Model	NP200 1.6 P/U S/C	
Vin	ADNUSN1D5U01959	923
Engine Specifications	1.6	Petrol
Vehicle Type	S/C	
Service Plan	N/A	

Year	2021
Km	119459
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	•	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Good Condition	•
Oil Filter	Renewed	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	Fan Belt	No Cracks	•
Air Filter	Within Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	Power Steering Belt	No Cracks	•
Brake Fluid	No Visible Leaks	Aircon Belt	Not Applicable	•
Antifreeze	No Visible Leaks	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	-
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	-

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Not Applicable	•
Aircon Pump	Not Applicable	•
Aircon Condensor	Not Applicable	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	No Fault Code	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	-
Auto Transmission	Not Applicable	-
Gear Selector	Good Condition	-
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

Raymond Mncube

NEW Technician

General Comments

Date of Inspection

09-May-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

