

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 2024-06-24 14:18:40

Technician Name: Basal

Order no:

Service fee:

Notes:

Vehicle Information

Year: 2019.12

Make: BMW

Model: 220i

VIN: WBA2H520307F58654

Displacement: G 1.2 MPI

Odometer: 57844 km

Vehicle Software Version: V10.30

Inspection Result

The following systems are OK:

- 1.ZGM (Central Gateway Module)
- 2.FRM (Footwell Module)/TSGFA (Driver Door Control Unit)
- 3.CAS (Car Access System - CAS/FEM/BDC)
- 4.GWS (Gear Selector Switch)
- 5.EPS (Electronic Power Steering)
- 6.ECM (Engine Control Module - DME/DDE)
- 7.LHMR (LED Main Light Module, Right)
- 8.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 9.TCM (Transmission Control Module - EGS)
- 10.ICM (Integrated Chassis Management)/RLM_2L (Tail Light Module, Inner Left)
- 11.ZBE/CON (Controller)
- 12.FZD (Function Center, Roof)
- 13.LHML (LED Main Light Module, Left)
- 14.ABS (Anti-Lock Braking System - DSC)
- 15.AC (Air Conditioning - IHKA)
- 16.ECALL (Emergency Call)
- 17.CIC (Car Information Computer)
- 18.IC (Instrument Cluster - INSTR)