

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:jaco@boschgezina.co.za
Sn:988579800333
Time:2024-05-13 14:45:20
Technician Name:Dries
Customer Name:cittoncars
Order no:
Service fee:
Notes:

Vehicle Information

Make:VW
VIN:WV1ZZZ2KZKX124926
Displacement:G 1.4 MPI
Odometer:143436 km
Vehicle Software Version:V10.23

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.16 Steering Column Electronics Systems
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.25 Anti-Theft Immobilizer
- 10.42 Driver's Door Electronics
- 11.44 Power Steering
- 12.52 Passenger's Door Electronics
- 13.56 Radio
- 14.61 Battery Regulation
- 15.69 Trailer Function