Make	VOLKSWAGEN		
Model	CADDY4 1.6i (81KW) F/C P/V		
Vin	WV1ZZZ2KZKX120377		
Engine Specifications	1.6 Petrol	~	
Vehicle Type	P/V		
Service Plan	N/A		

Year	2019
Km	141925
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	_
Cluster	Within Specification	•	Electric Windows	Not Applicable	lacksquare

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification		Aircon Belt	No Cracks	•
Antifreeze	Within Specification		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks ▼		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	
Rear Brake Sensor	Not Applicable	lacksquare
Rear Drums	Not Applicable	
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	lacksquare
Waterpump	No Visible Leaks	-
Thermostat	Within Specification	lacksquare
Aircon Gas	Within Specification	lacksquare
Aircon Pump	Good Condition	lacksquare
Aircon Condensor	Good Condition	V
Interior Fan	Good Condition	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	No Visible Leaks	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	—



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Within Specification	-
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	-
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	—

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	T
Gearbox	Within Specification	~
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	~
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	-
Handling	Good Condition	~

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	10-May-2024



