

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 13573

Make	HYUNDAI	
Model	H100 2.6D A/C F/C D/	/S
Vin	KMFZBX7BLJU54574	6
Engine Specifications	2.6	Diesel
Vehicle Type	D/C	
Service Plan	N/A	

Year	2018
Km	127044
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Not Applicable	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Good Condition	•
Oil Filter	Renewed	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	No Visible Leaks	Fan Belt	No Cracks	-
Air Filter	Within Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	Power Steering Belt	No Cracks	•
Brake Fluid	No Visible Leaks	Aircon Belt	Renewed	•
Antifreeze	No Visible Leaks	Multi V belt	No Cracks	•
Rear Main Seal	Not Applicable	Engine Mountings	Within Specification	-
Sump/Gasket	Not Applicable	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

Front Brake Pads100%Image: constraint of the section of the se	Braking System		
Front Brake SensorNot ApplicableFront Brake Pads-Select-Rear Brake DiscsNot ApplicableRear Brake SensorNot ApplicableRear DrumsWithin SpecificationRear Linings80%Brake MasterNo Visible LeaksHand BrakeWithin SpecificationBrake CalipersWithin Specification	Front Brake Pads	100%	•
Rear Brake Pads-Select-Rear Brake DiscsNot ApplicableRear Brake SensorNot ApplicableRear DrumsWithin SpecificationRear Linings80%Brake MasterNo Visible LeaksHand BrakeWithin SpecificationBrake CalipersWithin Specification	Front Brake Discs	Within Specification	•
Rear Brake DiscsNot ApplicableRear Brake SensorNot ApplicableRear DrumsWithin SpecificationRear Linings80%Brake MasterNo Visible LeaksHand BrakeWithin SpecificationBrake CalipersWithin Specification	Front Brake Sensor	Not Applicable	•
Rear Brake SensorNot ApplicableRear DrumsWithin SpecificationRear Linings80%Brake MasterNo Visible LeaksHand BrakeWithin SpecificationBrake CalipersWithin Specification	Rear Brake Pads	-Select-	•
Rear DrumsWithin SpecificationRear Linings80%Brake MasterNo Visible LeaksHand BrakeWithin SpecificationBrake CalipersWithin Specification	Rear Brake Discs	Not Applicable	•
Rear Linings 80% Brake Master No Visible Leaks Hand Brake Within Specification Brake Calipers Within Specification	Rear Brake Sensor	Not Applicable	•
Brake Master No Visible Leaks Hand Brake Within Specification Brake Calipers Within Specification	Rear Drums	Within Specification	•
Hand Brake Within Specification Brake Calipers Within Specification	Rear Linings	80%	•
Brake Calipers Within Specification	Brake Master	No Visible Leaks	-
	Hand Brake	Within Specification	•
Brake Hose Within Specification	Brake Calipers	Within Specification	•
	Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	~
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	~
Aircon Pump	Within Specification	~
Aircon Condensor	No Visible Leaks	~
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	~

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	-
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	-
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Within Specification	•
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

Raymond Mncube

NEW Technician

General Comments

Date of Inspection

21-May-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

