

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-05-27 14:15:13
Technician Name: Wimpie F
Order no:
Service fee:
Notes:

Vehicle Information

Make: RENAULT
Model: KWID
VIN: MEEBBA00600700064
Displacement: G 1.2 MPI
Odometer: 86504 km
Vehicle Software Version: V10.38

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS (Anti-lock Braking System)
3. IC (Instrument Cluster)
4. UCH
5. SRS (Supplemental Inflatable Restraint System)
6. Variable P.A.S
7. Radio